LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	
Benzie Located In: Corner Code #	
1. Public Land Survey T 26N R 15W M-5 T 26N R 14W A-5	
2. Property Controlling ST_R	
in Section STR	
3. Miscellaneous S T R	Bartatan of Bando Ciarro 8 Ello Numb
Property in Sec. S T R	Register of Deeds Stamp & File Numb
4. Lot No , Recorded Plat	
	A B C D E F G H I J K L M
5. Private Claims	2 6 5 3 2 - 1 - 1
	3
I, Craig W. McVean , in a field survey on April 15, 19 98 do	4 - 7 - 9 - 1 - 10 - 11 - 12
berehv state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner	
points mentioned in lines 1 and 2 above were in conformance with regulations and	
rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a	
Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above we	re i i i i i i i i i i i i i i i i i i i
in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered,	9 1 1 1 1 1 1 1 1 1
found as expressed below:	10-30-29-28-27-26-25-
NOTE: Not more than 2 corners, all in the same town and range, may certificate.	be recorded on this 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	
M-2 & M-2 - OFO OF BOSE SHAME THE STATE ST	-Co. Bk.,P. 138-139 - F. Haswell - 1894 (Sec.13,T26N,R15W)
Beech 13" N70°W 15L	Drove post 2'deep from OBT's -Co. Bk. II, P. 126 – F. Haswell (Sec. 7,T26N,R14W)
Do 5" S54°W 33L -GLO – Correct E. from post – Alvin & Austin Burt – 1839	Drove Iron Corner
T26N,R14W, Sugar 13" S65°E 8L	-R.M. Harris - File # 91-8-1496 - 1991
Hemlock 11" N43°E 17L	1" Pipe FND.
	14" Maple N20°W 13.13', 9" Maple S70W 19.80' 14" Maple S25°W 11.10', 10" Maple S71°E 16.30'
	-Rec. Survey L. 2, P. 331 – R.M. Harris - 1992
	FND. I. P.
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
M-5 & A-5 -Standard Corner common to Sec.'s 12 & 13, T26N,R15W, & Sec.'s 7 & 8, T26N,R14W. FND %" I.D. Iron Pipe apparently by Haswell and used by RMH. Fits distance N. well per Haswell. Distance E.&W. per Haswell is short; area very hilly. Find trace remains of fences N, W & E. CL. N-S 2 track is 8'± E. Accept Iron Pipe as the best available evidence of the position of the original corner.	
C. Description of monument for corner and accessories established to	perpetuate locating the position of the corner:
M-5 & A-5 -3/4" I.D. Iron Pipe. Add ring of stone.	OF MA
M-5 & A-5 -3/4" I.D. Iron Pipe. Add ring of stone. * N26°W 13.74' to set N&T in E. Side 18" S. Maple. * S18°W 11.08' to set N&T in W. Side 16" S. Maple.	
• S18°W 11.08' to set N&T in W. Side 10° S. Maple. • S75°E 16.33' to set N&T in S. Side 12" S. Maple.	
N41°E 50.93' to set N&T in SE. Side 8" Beech - scribed 'XBT'	
N71°W 22.67' to set N&T in S. Side 20" S. Maple - scribed 'XBT'	
Reset found guard pipe SW. 0.45' Set orange Carsonite post 1" N.	
Set orange Carsonite post 1" N.	₹ 39088
*RMH nail & shiner along side.	OPL 381()WI 32
a. m. M. a.	10/2 / 1000
Signed by Crang M. Mallow	Date 10/6 / 1770
Surveyor's Michigan License No. 39088	