LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF-:	LOCATED IN-:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 26 N. S., R. 13 E. W.	C-6, E-6, E-7
2. PROPERTY CONTROLLING IN SECTION 17	T. 26 N. S., R. 13 E. W.	14
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 10, 19 81, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

B. Continued: RLS, PE, survey & Sec. Sub'n. of Sec. 17 dated July 1939. Cor. also fits U.S. tie to definite swp. edge to west exactly & U.S. tie to swp. edge to S within 20' (U.S. plssed-in to nearest 1/2 chain).

E-7 CONT.

C. Continued:

E-7

Set DNR mon. & ced. post

10" Cedar	S20°W	5.6
20" W. Pine	S65°E	9.9
9" Cedar	N20°W	39.5

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-6 In 1968 during Dept. (KJO) survey of Sec. 18, an axle shaft w/gear was recovered for E1/4 cor. of Sec. 18. This gear has since been torn out; we were able to reestab. pos. per KJO survey which fits line across fd. Cade mon. N88°24'58"E, 33.00 R.O.W. Mon, 2632.83 ctr of Sec. 17, 5266.59 E1/4 cor of Sec. 17. Cor falls in approx. ctr. of winding N-S gravel rd. Trail road to West is approx. 60'North.

E-6 Fd. Sq. conc. mon. for E1/4 cor. of Sec. 17 as estab. by Cade in July 1939. Cor. is in approx. line w/trail rd. to N & W & 47'± W of trail rd. to SE.

14 Fd sq. conc. mon. as estab. in July 1939 by Cade, RLS & PE, for S1/8 cor on E side of S-17.

E-7 Reestab. SE cor. of Sec. 17 at dbl. distance & on line across fd. Cade mon's for 1/8 cor. & 1/4 cor. to N which fits fd. Cade mon's & his survey for S line of Sec. 17. See C.M.Cade

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-6

Drove 1 1/4" x 18" solid iron rod (buried 0.5)

4" Maple	N70°E	35.9
10" Maple(twin)	S50°W	34.6
7" Hemlock	S20°E	59.5

Fd. Cade mon. N88°24'58"E 33.0

Set ced post w/loc tag

East 33'

E-6

Fd. Cade mon. & added ced. post w/loc tag.

*17" Cherry	S55°E	3.39
*9" Maple	S70°W	20.4
9" Cherry	S05°W	57.4

*=Cade Wits.

14

Fd. Cade mon. & set ced. post w/loc. tag.

*11" Cherry	N05°E	25.5
*13" Cherry	S70°E	36.2
14" W. Pine	N50°W	24.2

*=Cade Wits.

SIGNED BY Carl F. Roser 02-10-82 DATE

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 (SEAL) REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

INLAND TOWNSHIP
BENZIE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET