

APR 14 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970 **LIBER 2 PAGE 69**

For corners in

BENZIE

(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|--|------------|
| 1. Public Land Survey | T <u>27</u> N R <u>13</u> W | <u>C-6</u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| 2. Property Controlling in Section | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| 3. Miscellaneous Property in Sec. | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |

STATE OF MICHIGAN
 BENZIE COUNTY
 RECORDED

15 Jan 1998 4:07:17 PM
 MICHELLE R. GRAY
 REGISTER OF DEEDS
 # PAGES one

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, CARL KIISKILA, in a field survey on OCTOBER 2, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18	●	17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:
 C-6

G.L.D. SET POST - 12" SUGAR MAPLE S40°W 17.2' AND 12" SUGAR MAPLE N51°E 9.9'. HAROLD R. BRUNING, 1974 L.C.R.C. SET BENZIE CO. MONUMENT ON PREVIOUS SURVEY. DNR SURVEY CREW FOUND BENZIE CO. MONUMENT FITTING HAROLD R. BRUNING 1974 L.C.R.C. AND WITNESSES.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 C-6

FOUND BENZIE CO. MONUMENT PER HAROLD R. BRUNING, 1974 L.C.R.C. AND WITNESSES.

Ratified by Peer Group
 In accordance with P.A. 345
 Chairman [Signature]
 Date 7/24/1996

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 C-6

FD BENZIE CO CAST IRON MON AND SET CARSONITE POST.
 11"S.MAPLE N14°W 31.07' (DROVE SPIKE W/BCRP TAG E. SIDE)
 #19" ASH N16°E 22.98' (DROVE SPIKE W/BCRP TAG SE SIDE)
 8"TM.S.MAPLE EAST 4.42' (DROVE SPIKE W/BCRP TAG S SIDE)
 #7"S.MAPLE S35°E 12.08' (DROVE SPIKE W/BCRP TAG NE SIDE) CTR OF BIT RD (IN CURVE NW & S) IS WEST 50' +/- 2'.

* = PS H. BRUNING 1974 WIT.



Signed by Carl T. Kiiskila
 Surveyor's Michigan License No. 33981

Date 4-9-97