SURVEY & REMONUMENTATION

AUG 1 0 1994

For corners in

COMMISSION

BENZIE COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATELIBER 2 PAGE 013 Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF BENZIE	MICHIGAN COUNTY
peri	101CI

Benzie	Located In:	Corner Code ##	RECORDED
(County)			neonine.
1. Public Land Survey	T <u>27N</u> R 13W	E-6	26 JUL 94 3:40 P.H.
			MICHELLE R. GRAY
			REGISTER OF DEEDS
2. Property Controlling	S T R		
in Section	S T R		
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
		•	•
	lecorded Plat		
5. Private Claims		· · · · · · · · · · · · · · · · · · ·	
			3
	بحاجب	102	4 - 7 - 8 - 9 - 10 - 11 - 12
	, in a field survey on 12 21		
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the			
current manual of survey instructions of the United States Department of the Interior, Bureau of Land			
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5			
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as			
expressed below:	e-established, monumented, re-mo	onumented, recovered, found	40
	orners, all in the same town and	d range man be useded	10 30 29 28 27 26 25
on this certificate.	officers, an in the same town and	range, may be recorded	
on and veranicate.	•		12 31 32 33 34 36 36 13 1 1 1 1 1
A. Description of original r	monument and accessories and/	or subsequent restoration:	13

E-6: GLO set Ironwood Post - 30" Hemlock N61°E 19.80'. H.R. Bruming, 1973, set 5/8" x 24" rebar by single proportion between corners to north and south. He recorded this corner in 1973 and subsequent surveys through 1978. Bob Mitchell, 1985, in L.C.R.C. Liber 1, Page 217, found square stone with plow point 18" below road surface and raised to surface with rod and cap.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-6: Reopened position found by Mitchell and found stone with plow point on west side below second gravel road bed. Also found remains of wood stake 28" below grade on west side of plow point. It appears that large stone was used to protect position of plow point and wood stake. H.R. Bruning corner is N45°E 6.09 feet. Bruning position was also recorded by Max Harris in 1992 in L.C.R.C., Liberl, Page 286.

> Ratified by Peer Group In accordance with P.A

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-6: Pulled stone, plow point and stake remains and remonumented position of plow point and stake with 3" Ø concrete monument with Benzie County Remonumentation Program Brass Cap in monument

Set Nail and tag in 10" Red Pine (with blaze) N43°W 45.82

Set Nail and Tag in 10" Red Pine West 44.38'

Set Nail and Tag in Twin 6" White Pine S40°W 60.42'

Found ½ x 18" rebar w/cap #10681 N83°E 37.53'

Found 5/8 x 2' rebar w/cap #10681 N85°E 6.14'

CENTERLINE OF N-S ROAD IS 1' EAST

Signed by DuB. Sweden	Date 7/26/94
Surveyor's Michigan License No	