

MAR 3 1 1994

2. Property Controlling

Property in Sec.

3. Miscellaneous

in Section

BENZIE COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN BENZIE COUNTY RECORDED

or corners in			
Benzie	Located In:	Corner Code ##	10 MAR 94 1:43 P.M.
(County)			COMPANY I P.
. Public Land Survey	T 27N R 13W	J-3	HICHELLE R. GRAY REGISTER OF DEEDS
	T R		
	T R		
	TΩ		

Register of Deeds Stamp & File Number

4.	Lot No, Recorded Plat	
5.	Private Claims	
		00

___ T R

S ____ T ___ R _

S ____ T ____ R ____

I, John B. Smendzuik, in a field survey on November 23 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	Α	В	C	D	E	F	G	Н	ı J	K	L	N
2] 6—	L	 5—		Ι 4—		3—	[\prod	_ [
3	_	_		L	<u> </u>		╙				_	
4	_	ļ 7—	_	 8	<u> </u>	 9 —	<u> </u> -	 0	T	\downarrow	_1	2
5	<u> </u>	 	<u> </u>		<u> </u>		ļ	<u> </u>	\sqcup	\dashv	_	
6	L ₁	 8—	L,	 7	1	6		 5	14		_{1	3
7		ļ			<u> </u>	<u> </u>	<u> </u>				_	
8	<u> </u>	9	L_2	0	L_2	 	Ļ	 22	23	,	2	4
9		 	<u> </u>		_		ļ	-	1	4	_	
10	<u> </u> 3	0—	<u>_</u> 2	9—	<u>_</u> 2	 8	-2] 27—	26	-	<u>.</u>	5
11	<u> </u>	<u> </u>	<u> </u>		_	<u> </u>	ļ	<u> </u>		_	4	
12	<u></u> ∟₃	1	<u> </u> _3	2—	<u> </u>] 3—	Ļ	4	35	<u>-</u>	3	6-—
13	L	L	L_		_	<u> </u>	L_				_	

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

- A. Description of original monument and accessories and/or subsequent restoration:
- J-3: G.L.O. See Beech post 12" Beech N61°W 21.78' & 6" Beech S52°E 9.90', Benzie County Ros Commission (B.C.R.C.) in 1970 had a large cut in area removing all evidence of corner position B.C.R.C. reset railroad spike by single proportion. B.C.R.C., 1971, found 1/21 iron pipe set t Batzer. Subsequent surveys by Gourdie Fraser Associates show found iron pipe.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - J-3: Found P.K. Nail in road surface over 1.D. by 1/2 0.D. iron pipe. Iron pipe fits a singl proportionate position reasonably well. Iron pipe fits witnesses previously taken by B.C.R.C and Gourdie Fraser and Associates. Iron pipe is in centerline of East-West Road.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - J-3: Pulled iron pipe and set 3" Ø concrete monument in a monument box with Benzie County Remonumentation Program Brass Cap.

Set double headed nail and brass tag stamped B.C.R.P. in the following:

33" Maple N43°E 50.43' (South face) Twin 14" and 12" Maple N35°W 79.76' (Southwest face) Power Pole S24°E 67.05' Concrete monument S4°W 32.99'

Signed by	She shit	Date 3/10/94	
Surveyor's Michigan License No.	30895	FORM ADDROVED BY MICHIGAN STATE ROOM	ARD DE LAND SHAVEYORS JAN 28, 19