## SURVEY & REMONUMENTATION

MAY 0 5 1997

LIRER 2 PAGE 49

الاخلام حسد		_	 	

\_\_\_ , Recorded Plat \_

For corners in

5. Private Claims \_\_\_

on this certificate.

LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN BENZIE COUNTY

	Benzie	Located In:	Corner Code ##	RECORDED
	(County)		301101 3040 77	1/22/1997 1:54:36 P
1.	Public Land Survey	T 27N R 13W	L+5	MICHELLE R. GRAY
		T R		REGISTER OF DEEDS
		T R		# PAGES
		T R		
2.	Property Controlling	S T R		
	in Section	S T R		•
3.	Miscellaneous	S T R		Register of Deeds Stamp & File N
	Property in Sec.	S T R		register of Decas Stamp & The N

Ħ

umber

I, John B. Smendzuik, in a field survey on _	December 17	
do hereby certify that under requirements of P.A. 74, Mic	higan P.A. of 1970, the corner	pointsmentioned
in lines 1 and 2 above were in conformance with regu	lations and rules therefore	as required in the
current manual of survey instructions of the United Sta	ites Department of the Interio	or, Bureau of Land
Management or by a decree of a Court of Law and/or tha	t the corner points mentioned	l in lines 3, 4 and 5
above were in conformance with the rules of the Michig	an Board of Land Surveyors	or by a Decree of a
Court of Law; established, re-established, monume		

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded

		ъ.	<u> </u>		_	F	G	п	,	, ,		IV
2	L	6		[ 5—	L.	 	L,	3		2		_
3	<u> </u>	lacksquare	<u> </u>	<u> </u>	_	<u> </u>	<u> </u>	<b> </b>				_
4	L	ļ 7—	<u> </u>	 8	L,	9—	L	ا 0—	L,	ļ	1	2
5		↓_	<u> </u>	<u> </u>	<u> </u>		_	ļ	ļ			_
6	Ļ	  8—	1	7	ļ <sub>1</sub>	6—	L_1	[ 5—	L,	4		] 3—-
7		┞	<u> </u>		L	<u> </u>	_	<u> </u>				
8	L-1	9	<u> </u> -2	0	2	1	2	 2	2	3—	2	4—
9		lacksquare	┡	ļ				Щ				_
10	L.	 30	ļ <sub>2</sub>	9	_2	8	_2	ا ا—	2	6	2	5
11	_	┞	▙	ļ		L_				Щ	$\Box$	
12	ļ.,	<u> </u> _	L3	2	<u> </u>	3	3	4	3	5	3	6
13	L	$oxed{oxed}$			L							

A. Description of original monument and accessories and/or subsequent restoration:

L-5: G.L.O. set post and witnesses: 20" Beech N35°E 21.12' and 30" Hemlock S87°W 5.94'. Surveyor's Record II, Pg. 136, James Pettit set a 1 1/4" well point equidistant between adjacent corners to East and West. Certificate of Survey, dated 12/14/1978 and recorded in Liber 1 of Surveys, Page 608, by Bill Batzer shows he found 1 1/4" well point and set a 1/2" iron rod over it.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

L-5: Found 1/2 iron rod over 1 1/4" well point fitting witnesses from survey noted above.

Ratified by Peer Group In accordance with P.A Chairman\_ 12/12/95 Date\_\_

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- L-5: Removed iron rod and well point and set 3" diameter Benzie County Remonumentation Program concrete monument 5" below grade of gravel road intersection.

Twin 14" & 20" Maple N41°E 55.50' 32" Maple N72°E 39.72' Power pole N87°E 99.79

Power pole S26°W 54.72'

Signed by Signed by	Date	1/21/97	
Surveyor's Michigan License No	Date		