LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	
Benzie Located In: Corner Code #	
1. Public Land Survey T 27N R 14W C - 12 T R T R	
2. Property Controlling S T R	-
in Section S T R	
Property in Sec. S T R	Register of Deeds Stamp & File Numb
4. Lot No, Recorded Plat	A B C D E F G H I J K L M
5. Private Claims	2 6 - 5 4 - 3 - 2 - 1 - 3 3 4 - 7 - 8 9 10 - 11 - 12
I, <u>Craig W. McVean</u> , in a field survey on <u>July 13</u> , 19 <u>98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	5 6 18 17 16 15 14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -13 -14 -14 -13 -14 -14 -14 -14 -14 -14 -14 -14 -14 -14
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	13'
A. Description of original monument and accessories and/or subsequent restoration:	
C-12 - GLO - Set Ort Sec Post - J. Hunt - 1850 Beech 18" N85°W 26L Beech 10" S43°E 25L - Gourdie- Fraser & Assoc File # 76891 - subdivided S-32 - 1976 Maple Clp. S10°E 23.67' 9" Maple S35°W 17.30' Fences N. at W. 0.5'	
B. Description of corner evidence found and/or method applied in restoring or reestablishing	ng corner:
C-12 - ¼ Corner common to Sec.'s 31&32. Found RailRoad Rail 17" up x 4' long w/ cross noted in Gourdie- Fraser & Assoc. field notes. Fits their Cert. of Survey in S 1/2 of falls on SE side of anchor post for fences N, W, & S. Center of B. Top road (NW accepted as the best available evidence of the position of the original corner.	of S-32, File # 76891. Monument
C. Description of monument for corner and accessories established to perpetuate locating the	ne position of the corner:
C-12 - Replaced found RR rail with Benzie Co. Concrete Monument in ring of stone. 4" Sugar Maple N30°E 4.03' 3" Ironwood S70°E 11.32' 9" Triple Sugar Maple S10°E 23.65' 12" Sugar Maple S35°W 17.32' NW. 0.7' to 8" wood anchor post N. 1' to orange Carsonite post = Gourdie- Fraser & Assoc. Witnesses.	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. 39088
Signed by Craig M Me Ven	Date 9/29/1998
Surveyor's Michigan License No. 39088	/ /