

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

BENZIE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 27N R 14W

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling in Section

S 13

T _____ R _____

S 25

T _____ R _____

3. Miscellaneous Property in Sec.

S _____

T _____ R _____

S _____

T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, CARL T. KIISKILA, in a field survey on JULY 1, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:
 14 _____ 1 _____

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

ESTABLISHED THE NE COR OF THE SE1/4 OF SE1/4 OF SEC. 13 PER STANDARD BLM PROCEDURE. CTR OF TRAIL, NW-SE, IS 302' +/- NORTH AND 80' +/- EAST.

ESTABLISHED THE NE COR OF W1/2 OF NW1/4 OF S-25 PER STANDARD BLM PROCEDURE.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

14
 DROVE 5/8"x 3/4" REROD W/PS CAP, SET CEDAR POST W/LOC TAG.
 3" MAPLE N15°W 18.5'
 4" MAPLE N60°E 25.0'
 7" MAPLE S10°E 7.0'
 13" W.PINE S70°W 12.9'

1
 SET 5/8"x 3/4" REROD W/PS CAP & CARSONITE POST W/LOC TAG.
 3" R.MAPLE N26°E 6.92'
 3" ELM S34°E 14.14'
 3" R.MAPLE S60°W 11.53'
 5" TN.R.MAPLE N30°W 32.14'
 N-S TRAIL WEST 115' +/-

Signed by Carl T. Kiiskila
 Surveyor's Michigan License No. 33981

Date 4-9-97