LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	raing Requirement of Act 74, Mich.	P.A. 1970
BENZIE	and the second of the	
(County)	Located In: Corner Code #	
1. Public Land Survey	T_27N R_14N	
2. Property Controlling in Section 3. Miscellaneous Property in Sec.	TR	Register of Deeds Stamp & File Number
4 Lot No. Beco	orded Plat	
	JUGO Flat	A B C D E F G H I J K L M
requirements of P.A. 74, Michig conformance with regulations an United States Department of the that the corner points mentione	, in a field survey on	3
	mers, all in the same town and range, may be recorded	9
on this certificate.		10 30 29 28 27 26 25
		12 31 32 33 34 35 36
J-9	conument and accessories and/or subsequent restoration: ECH 515°N 26.4' AND 16" SUGAR MAPLE N45 E 45.5'. NO EVID	DENCE OF THIS G.L.O. POST OR BEARING TREES WAS
J-9	ridence found and/or method applied in restoring or reestablic SINGLE PROPORTIONATE MEASUREMENT BETWEEN FOUND CORNER TO	
C. Description of monumen	it for corner and accessories established to perpetuate locating	ng the position of the corner:
SET 4"x 36" CONC. MON W/E BRASS CAP. SET CARSONITE 12"B.CHERRY N75"W 2 6"B.CHERRY N25"W 4 7"TW.B.CHERRY N55"E 4	POST. 24.06' 42.59' 49.14' 7.28'	CARL KIISKILA LAND SURVEYOR No. 33981
Signed by Call	T Kuskila Da	4-8-97
Surveyor's Michigan License	33981	