

✓
MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD


T. 27 N.R. 15 W
T. 26 N.R. 15W BENZIE COUNTY

DESCRIPTION OF CORNER Sec. corner common to Sections 33-34-3-4

CORNER MONUMENT Found 1/2" pipe in gravel road

DATE MONUMENT PLACED AND WITNESSED June 1968

WITNESSES TO CORNER.....



12" Maple N 25 W 29.3'

9" Maple S 45 W 30.9'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner fits F. Haswell survey of Section 4, T26N, R15W of 1914 and on record at County Courthouse.

SURVEYOR'S SEAL

SIGNED Paul F. Doer DATE 7/8/68
REGISTERED LAND SURVEYOR
12028