

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 27 N.R. 15 W


BENZIE COUNTY

DESCRIPTION OF CORNER M.C. common to sections 31-32, N Side Long Lake

CORNER MONUMENT Found 1 1/2" pipe

DATE MONUMENT PLACED AND WITNESSED June 1968

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

7" Cedar S 27 E 32.2'

12" B. Cherry N 55 W 22.0'

AND
12" W. Birch N 18 E 51.7'

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner is the corner as noted on Page 78, County Surveyor's Book at County Courthouse, by F. Haswell.

SURVEYOR'S SEAL

SIGNED Carl F. Roer DATE 7/9/68
REGISTERED LAND SURVEYOR

12028