

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


BENZIE COUNTY  
T 27 N R 18 W

DESCRIPTION OF CORNER E/4 corner common to Sections 1 & 12

CORNER MONUMENT Found 3" pipe. Left in place.

DATE MONUMENT PLACED AND WITNESSED 12-2-70

WITNESSES TO CORNER,..... Wits. by Fraser - Nail in side of tree



12" Oak N 40 W 4.3' to Nail

10" Oak S 35 W 18.1' to Nail

AND

10" Beech N 75 E 26.3' to Nail

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner was recovered while making a boundary survey in this area. This is an old corner of which Walt Fraser, RLS, Traverse City, has record of. He recovered and used the corner to subdivide Sec. 12, in 1969.**

SURVEYOR'S SEAL

SIGNED

*Carl F. Ross*  
REGISTERED LAND SURVEYOR 12028

DATE

12-9-70

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68