


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

BENZIE COUNTY
T 27 N R 15 W

DESCRIPTION OF CORNER C 1/4 corner Section 12
CORNER MONUMENT Drive 1" x 36" pipe & 5" cedar post
DATE MONUMENT PLACED AND WITNESSED 12-7-70
WITNESSES TO CORNER..... 10" Cedar S 31 W 16.6'
10" Cedar S 87 W 22.7'
9" Cedar N 29 W 27.1'
AND



CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set while making a boundary survey in this area. The corner was set at the intersection of the 1/4 lines, based on a survey of Section 12, by Walt Fraser, NLS, Traverse City.

SURVEYOR'S SEAL

SIGNED

Carl F. Roese
REGISTERED LAND SURVEYOR

DATE

12-14-70

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68