

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


BENZIE COUNTY
T 27 N R 15 W

DESCRIPTION OF CORNER 1/4 corner common to Sections 14 & 23 23

CORNER MONUMENT Found Benzie County Monument

DATE MONUMENT PLACED AND WITNESSED 12-4-70

WITNESSES TO CORNER..... Witnesses by Perla - Drummig, Nail in trees



12" Oak N 88 E 9.75'

9" Oak N 82 W 32.35'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered while making a boundary survey in this area. The 1/4 corner is the result of a retracement survey by Perla & Stout, RLS, Traverse City and Harold Drummig, RLS, Beulah.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Carl F. Rosen
REGISTERED LAND SURVEYOR

DATE 12-11-70

12-11-70

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing