

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


BENZIE COUNTY
T 27 N R 18 W

DESCRIPTION OF CORNER S 1/16 corner common to Sections 13 & 14

CORNER MONUMENT Found 4" Round concrete monument. Left in place.

DATE MONUMENT PLACED AND WITNESSED 12-4-70

WITNESSES TO CORNER..... 11" R. Pine N 47 E 11.9'



13" W. Pine S 20 E 12.9'

8" W. Pine S 32 W 12.8'

AND

10" R. Pine S 77 W 10.0'

CIRCLE CORNER REGISTERED

In slope of sand dune N-W

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered while making a boundary survey in this area. The corner was placed for the SE corner of Govt. Lot 1, Sec. 14, by Parla & Stout, RLS, Traverse City, during retracement survey in this area.

SURVEYOR'S SEAL

SIGNED

Carl F. Rosen
REGISTERED LAND SURVEYOR 11028

DATE

12-11-70

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing