

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

✓


BENZIE COUNTY  
T 27 N R 15 W

DESCRIPTION OF CORNER Sec. corner common to Sections 11-12-6 13-14

CORNER MONUMENT Found Benzie County Monument

DATE MONUMENT PLACED AND WITNESSED 12-4-70

WITNESSES TO CORNER..... 14" Cedar N 50 W 8.2'



14" Cedar N 35 E 8.6'

9" Cedar S 55 E 39.1'

AND 7" Cedar S 12 W 18.8'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner was recovered while making a boundary survey in this area. The section corner is the result of a retracement survey in the area by Perla & Stout, RLS., Traverse City, and Harold Bruning, RLS, Baulah.**

SURVEYOR'S SEAL

SIGNED Carl F. Breen DATE 12-11-70  
REGISTERED LAND SURVEYOR 19028

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing