

✓

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


BENZIE COUNTY
T 27 N R 18 W

DESCRIPTION OF CORNER C 1/4 corner to Section 14

CORNER MONUMENT Found 4" round concrete monument. Left in Place.

DATE MONUMENT PLACED AND WITNESSED 12-8-70

WITNESSES TO CORNER.....



8" W. Pine	S 55 W	247.8'
12" W. Pine	S 35 E	251.0'

AND
In sandy open area.

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered while making a boundary survey in this area. The concrete monument was placed by Parla and Stout at the intersection of the 1/4 lines during a retracement survey in this area.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Carl F. Rosen

DATE

12-11-70

REGISTERED LAND SURVEYOR **12028**

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing