144 - 3 1939 . SECTION	LAND CORNER RECOR		LIBER 2 PAGE 245
For corners in	· · · ·		STATE OF MICHIGAN
Benzie (County)	Located In:	Corner Code #	BENZIE COUNTY RECORDED
1. Public Land Survey	T 27N R 14W	F-13	27 JAN 1999 9:11:09 AM MICHELLE R. GRAY
2. Property Controlling S	T R T		REGISTER OF DEEDS
in Section S 3. Miscellaneous S	TR		
Property in Sec. S	TR		Register of Deeds Stamp & File Num
4. Lot No, Recorded Plat			
4. Lot No, Recorded	Plat		A B C D E F G H I J K L H
5. Private Claims			2 - 6 - 5 4 3 2 1 - 1
5. Thvate Claims			4 7 8 9 10 11 12
I, Craig W. McVean_, in a field s	urvey on Jul y 6, 19 98	do hereby	5
state that under requirements of P.A. 74, mentioned in lines 1 and 2 above were in	Michigan P.A. of 1970, the cor	ner points	6 -1'8 -1'7 -1'6 -1'5 -1'4 -1'3 -1
therefore as required in the current manual	al of survey instructions of the U	Inited	8 19 20 21 22 23 24
States Department of the Interior, Bureau Court of Law and /or that the corner poin	ts mentioned in lines 3, 4 and 5	above were	9
in conformance with the rules of the Mich Decree of a Court of Law; established, re-	igan Board of Land Surveyors o	rbya 🔌	10-30-29-28-27-26-25
found as expressed below:	: .	70.00,	
NOTE: Not more than 2 corners, a certificate.	II in the same town and ran	ge, may be recorded on this	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:			
F-13 & F-1 - GLO - Set Post - J. Hu	nt - 1850		
Beech 8" N62°E 39L - Co. Surveyor Notes - Small Bk. L., P. 121 - D.F. Holden - 1880 - Rec. Survey - L. 1,Page 436 - W. Batzer - 1976			
For survey of S-4 T26N R14 W "FND buggy axle?"			
"At B found the old witness trees prety [sic] badly decayed, perpetuated 6" Maple N52.5°E 64.97' by Hemlock stake with pieces of stove plate and a broken plow point 16" Maple West 30.85'			
around it, and over these several stones." 4" Maple N34°W 86.62'			
- Co. Survey Record - P. 4 - J. A. Pettitt - No date - Rec. Survey - L. 2, P. 248-250 - R.M. Harris -1992 Shows Found Iron stake			
"Set cedar post equidistant between 1&2 - No timber near." -Co. Survey Record - G. Langford - No date "Cedar post, 4"x4"x3" long." Shows Found Iron stake			
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:			
point along E. side. Cor. is in line with B. 1 (cut off) between grav Monument at F-13 - N would be 12′ + East of Holden had original Gl	or. fits 1976 Cert. of Surve Fop road E & S, gravel road el and B. top roads. Found lo Crockery or stones found of Holden's position based o	by Li. 1, P. 436 by W. Batzer, N & down fence remains to the small 1/2" Boat spike 3.7' Note. It would appear that Pettitt in Monumentation at the C S nument of Plow point and Iron	nd 1 1/4" x 20" long Iron Pin, with Plow PS #13026 in NW 1/4 S-4, T26N, R14W. he W. Cor. is 2' E of center N-S trail road orth. Plow point fits description of Holden's and Langford used a S.P. position that 1/16 and the C 1/4 of S-33 by Langford. In Pin accepted as a careful and faithful
C. Description of monument for cor	ner and accessories establis	hed to perpetuate locating the	e position of the corner:
F-13 & F-1 - Replaced Iron Pin and Set Carsonite Post wit * 30" Sugar Maple Wes * 30" Sugar Maple N25"	h location tag West 33'. t 30.78' W 38 79'	· . •	f stone, down 1'.
^24" Beech N60°E 58.1	2' Ratified	d by Peer Group	CRAIG W.
*12″ Sugar Maple N35° *12″ Sugar Maple N50°	E 64 0E' (rdance with P.A. 345	
* = W. Batzer 1976 Witnesses. Date June 24, 1998			
* = W. Batzer 1976 Wi ^ = Witnesses by other		Jane 24 City	PROFESSIONAL SURVEYOR No. 39088 SET NO. 39088
n · m.	ma ai		9/30 11000
Signed by Cray III.	/Vallea-		Date 9/29 //998
Surveyor's Michigan License No	39088	· · · · · · · · · · · · · · · · · · ·	