SURVEY &	NOI
----------	-----

APR 1 4 1998

LIBER 2 PAGE 81

SECTION	CTION
---------	-------

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN BENZIE COUNTY RECORDED

For corners in			·
DENTIE	Located In:	Corner Code #	15 Jan 1998
(County)		1	HICHELLE R
1. Public Land Survey	T <u>27N</u> R <u>14M</u> T R	<u>H-7</u>	REGISTER OF # PAGES _C
•	<u>TR</u>		
	TR		
2. Property Controlling in Section	S 1R S TR		
3. Miscellaneous	s TR		Register of Deeds Stamp &
Property in Sec.	S IK		Register of Decay County

4:10:37 PM . GRAY F DEEDS ne\_

File Number

4, Lot No,	Recorded Plat
5, Private Claims _	

, in a field survey on <u>OETOBER 3</u>, 19 96 do hereby state that under i, LHRL KIEDKILH , in a field survey on UETBBER 3, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	. B	С	ם	E	F	G	Н	I	J	ĸ	L	М
1 Î	Ť	Ť	Ť	T	$\top$		$\Box$		.			
2	<del>(</del>	5	<u>\$</u> -	+	- 4·	_	— 3 	$\neg$	2 1		- i	$\neg$
3		-		+	十	_	一					
4	<u>'</u>		8-	-	و ا	+	—10 I	١	1 	1	1: 	2-
5			-	+	十	-+	$\dashv$	$\neg$	-			
6	<del> </del> 1	8	17	+	16		1	5	1	4	1 	3
7	}		┢╼┼	-	十		-					
8		<u>'</u> 9	-20	-	2	<u>1—</u>	2	2	<del> 2</del>	3 I	-2	4 
9	<u> </u>	<u> </u>	_	-	{							-
10		30	25		2	8	2	!7	<del> </del>	-6	-2	5— 
1:	<u> </u>	┼-	┼╌┼				_	-	-	<del>                                     </del>	<del> </del>	
12	2	3,1	32		3	3 I	<del> </del>	34— 	╁	35 	<del>                                     </del>	36 
	.1	l	1		لـــا		L	L	┸-	Ь—		

A. Description of original monument and accessories and/or subsequent restoration:

Surveyor's Michigan License No.

6.L.O. SET POST - 12" BEECH 620°E 17.2', 8" SUBAR MAPLE N14°W 21.1', 1850 RESURVEY OF SUBDIVISION OF TOWNSHIP. NO EVIDENCE OF THIS 6.L.O. POST OR WITNESS TREES WAS FOUND. FOUND 1/2" PIPE 12.3' EAST OF CALCULATED SINGLE PROPORTIONATE POSITION PER R.MAX HARRIS, PS #25845, CERTIFICATE FITTING HIS WITNESSES. AFTER A DISCUSSION WITH M. HARRIS IT WAS DETERMINED THAT A TEMPORARY POINT WAS APPARENTLY WITNESSED IN ERROR.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SET 51/4 CORNER SEC. 15 MIDWAY AND ON LINE BETWEEN FOUND SECTION CORNER TO THE WEST AND REESTABLISHED SECTION CORNER TO THE EAST. CORNER FITS M.HARRIS CERT. OF SURVEY DATED JUNE 19, 1991; FILE NO. 91-6-1465. CTR OF OLD RR GRADE, NOW TRAIL ROAD, NE-SM IS 66' WEST. FD OLD 1 1/2"x 12" SOLID IRON, BENT, N70°W 28.9'. Ratified by Peer Group

In accordance with P.A Date.

C. Description of monume H-7 SET D.N.R. MON. & CEDAR 26" B.CHERRY N25°E 16" B.CHERRY N95°E 14" MAPLE S50°E 13" TW.B.CHERRY S25°E FD 1/2" REROD W/RLS CAP S87°W	37.05° 57.04° 48.19° 38.71°	<del>j</del>	CARL KIISKILA LAND SURVEYOR No. 33981
(i) a	- 010.0	W-8-97	