

APR 1 4 1998

LIBER 2 PAGE 92

SE) N
n 3 L	_	 A 11

For corners in

4. Lot No.

5. Private Claims

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN BENZIE COUNTY RECORDED

BENZIE	Located In:	Corner Code#
(County)		
1. Public Land Survey	T <u>27N</u> R TR TR	14W I-13
Property Controlling in Section	S TR_ S TR	
Miscellaneous Property in Sec.	S TR_ S TR_	

, Recorded Plat

15 Jan 1998 4:13:09 PM MICHELLE R. GRAY REGISTER OF DEEDS # PAGES One

Register of Deeds Stamp & File Number

I, CARL T. KIISKILA , in a field survey on OCTOBER 7 , 19 96 do hereby state that und	er
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were	in
conformance with regulations and rules therefore as required in the current manual of survey instructions of the	10
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and / that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michiga	Ol.
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumente	d.
maniformed formed an exercised bulletin	-,

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A 1	В	C I	2	E :	F	3 1	i	Ī.	J	K :	L t
2	_	I 6—	<u> </u>	 5	L	 4	L :	 3 —	Ľ	2-	1_	 1
3		L.	<u> </u>	<u> </u>	<u> </u>	<u> </u>		L	<u></u>	Ĺ		Ĺ
4	L.	ļ 7—] 8—	L	 9—	<u></u> ևլ	 -	L	 11—		12
5			<u> </u>			Ĺ				Ī		Ĺ
	,	Ĭ		_	١.	6—	١.	_			Ι,	
6	1	. 8	,	ľ	Γ,	i—	,	5— 	Γ	14— 	Ţ_,	.3
	7		Ι,		<u> </u>]		
8	<u>-</u> T	9 	 	0— 	_\'	1	2	2 		23 <u>—</u> 	 	:4
9		1						-	-	-	 	-
10	—3	io— I	 	9	2	8	2	7	-	2'6 1	2	5 I
11			\vdash				-	-		+		
12	—3	1—	 3	2	 3	3	3	4	-	35	3	6
13	L	L	<u>L</u>		[<u> </u>		

A. Description of original monument and accessories and/or subsequent restoration:

I-13

U.S. G.L.O. - SET POST COR SEC'S 34 & 35; BEECH 11 N50W 33.7', BEECH 8 N58E 24.4', OLD NOTES FD AT BENZIE CO. RD. COMM CALLS FOR "IRON PIPE 1 1/4" PIPE".

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

ON 11-5-92 DNR SURVEY CREW FOUND 1/2" REROD W/M.HARRIS PS CAP; ON 10-7-96 DNR CREW FD 1/2" REROD W/PS CAP OVER OLD 1 1/2" WELL SCREEN AND REPLACED W/BCRP MON.

> Ratified by Peer Group In accordance with P.A.

> > CARL

KIISKII A

LAND

SURVEYOR

No. 33981

J,	Description	n ot moni	ument for	corner and	d accessories	established to	perpetuate	locating the position	of the corner:
	I-13							• •	

FD 1/2"x 18" REROD W/PS CAP & BOTTOM 13"x 1 1/2" OLD WELL SCREEN, REPLACED W/4"x 36" CONC. NON W/BCRP BRASS CAP. CTR OF E-W GRAVEL RD. IS 9' SOUTH, CTR OF GRAVEL RD TO SOUTH IS 5' EAST.

FD BENZIE CO MONINE S-3, T26N-R14W

S88 58'E 14.77' 43.54'(NAIL & TAG NE SIDE)

13"S.MAPLE 16" S.MAPLE

Nº0°W N35°E

47.69' (NAIL & TAG SE SIDE)

10" MAPLE S45°E

80.66' (NAIL & TAG NE SIDE)

18" MAPLE(CLP-4) S30°W 48.25'(NAIL & TAG NW SIDE)

SET CARSONITE POST N/LOC TAG NORTH 33'. SW COR E1/2 OF SE1/4 OF SE1/4 OF S-1/4, SET 5/8"x 34" REROD W/PS CAP N89°20'W 659.64'

Carl T Kushila

4-9-97 Date

Surveyor's Michigan License No.