SURVEY & REMONUMENTATION

APR 1 4 1998

LIBER 2 PAGE 107

SECTION LAND CORNER RECORDATION CERTIFIC Filing Requirement of Act 74, Mich. P.A. 19	970
BENZIE Located In: Corner Code #	STATE OF MICHIGAN BENZIE COUNTY RECORDED
1. Public Land Survey T_27N R_14N	15 Jan 1998 4:17:35 PM MICHELLE R. GRAY REGISTER OF DEEDS # PAGES ONE
2. Property Controlling S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
5. Private Claims	ABCDEFGHIJKL
	2 6 5 4 3 2 1 1
L PARL T VITRALIA	3
I, <u>CARL T. KIISKILA</u> , in a field survey on <u>SEPT. 27</u> , 19 <u>96</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	4 7 9 10 11 12
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or	5 17 16 15 14 13
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Soard of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,	7
recovered, found as expressed below:	8 -19 -20 -21 -22 -23 -24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate.	10 30 -29 -28 -27 -26 -25
	11 32 33 34 35 36
	12 31 32 33 34 35 36
M-13 6.L.O BEECH 7" S22°W B LK5 (5.3'), BEECH 6" N21°N 27 LKS (17.8'). 6EO. STEEL, JULY 23/24 1868 - N.B.T. HEMLDCK 12 N86°E 33 (21.8'); SUGAR 24 N27°N 60 (39.6').	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
M-13 REESTABLISHED SE COR S-36 (4-TWP COR.) ON AVERAGE CTR LINE OF IRREGULAR 2-TRACK TO EAST & AVG. LINE OF 30' TO 33' OLD R/N FENCE TO EAST, THAT IS ON S'LY SIDE OF 2-TRACK TO EAST; AND ON LINE OF CEDAR POSTS & FENCE REMAINS TO SOUTH. CTR. OF TRAIL ROAD (SW - NE) IS 3' NN'LY. REMAINS OF OLD CORNER FENCE POST HOLE IS 30' SOUTH.	
Ratif	ied by Peer Group
	ccordance with P.A. 345
Chairn	12/18/95
Date_	
C. Description of monument for corner and accessories established to perpetuate locating the post #-13	sition of the corner:
SET 4"x 36" CONC. MON ENCASED IN STEEL PIPE W/CONS. DEPT. BRASS CAP. B"TRI.MAPLE N15°W 29.0'	CARI CARI
11"MAPLE(CLP-7) N45°E 23.4' 7"MAPLE(CLP-4) S75°E 49.6' 10"MAPLE N80°N 27.7'	KIISKILA LAND SURVEYOR
	33981 8 33981 8
Signed by Carl T. Kirkila Date 4	0 92
77/04	-8-97
Surveyor's Michigan License No	