, -				<u>{</u>			RECOR						
RA1 S	IFIED BY THE BERRI SURVEY PEER GROUP	EN COUL	YTV					•					
OF F I	CIAL CORNER UNDER	MICHIO 1990	SAN	BERRI	EN COUNTY F	REMONUMEI	NOITATION	<i>ኮ</i> የነ ነ	*n 10	6 14 <i>i</i>	- ^		
	Acola		ı	LAND CO	ORNER RECO	RDATION CE	RTIFICATE	00 51	:r 13	PM I:	53		
+	B-22-0	ر اح		Filling	PRNER RECORD Requirement of	Act 74, Mich. P.	.A. 1970	NY LAZI REC NACRAIN	MCE TR SISTER I	ETKE#AY OF LUTENES T Y. MI 9HH	#1497 } እሱዚ _{ግግ}		A66 \$7.00
Fo	corners in				МА Т			UTTION	3 () 0 0 0 11	~ ~ ~	REMON		A66 \$2.00
BE	ERRIEN COUNTY	***********	************	Located	in: Corner	Code #							
1.	Public Land Survey				A-11 SW CORNER, SE								
2.	Property Controlling in Section			R R	*************************		Regist	er of De	eds Sta	mp & File	Numb	er	
3.	Miscellaneous				*******					F G ł	1 1 1	κι	м
	Property in Sec.				*******************			Î	` 	fii	<u>' i i i</u>	Î	
4.	,,							2	┝━╅╼╅	─ ╅ ╌ ┼─╡	-	1	一
5.	Private Claims	**********		************		129724		3	┝┼┼	- - - 		+	7

I, George J. Mitchell....., in a field survey on ...June 28 & Aug. 28, 2000.... do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3. 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

APRIL 1827 WILLIAM BROOKFIELD D.S. - WEST BETWEEN SECTIONS 19 AND 30 AT 81.55 CHAINS, INTERSECTED WEST BOUNDARY 30 LINKS SOUTH, SET POST 18 W. OAK - N27°E - 37 LINKS & 12 W. OAK - S50-1/4°E - 38 LINKS

1920 DEWEY & 1944 G.L., WIGHTMAN - FIELD NOTES SHOW THE MEASUREMENT OF 2632.3 FEET NORTH TO QUARTER POST AND 19.8 FEET SOUTH OF T3S, RA8W CORNER.

AUG. 1973 - R. GARRETT, P.S.- L.C.R.C. OF RANGE 18 CORNER USES IRON PIPE 19.00 FEET SOUTH AS A WITNESS.

SEPT. 1981 - J. G. KAMAR, P.S. - P.A. 132 SURVEY IN THE NW1/4 OF SECTION 36-3-18, USES IRON PIPE 19.00 FEET SOUTH AS A WITNESS TO M-11 RANGE 18 WEST CORNER.

- G. J. MITCHELL AUG. 2000 FOUND WELL POINT AND 1 INCH PIPE 17.0 FEET SOUTH FROM ABOVE CORNER HISTORY. ALSO FOUND 3/4 INCH PIPE 19.8 FEET SOUTH OF 1INCH PIPE. MEASURED NORTH FROM 3/4 INCH PIPE 2630.1 FEET (RECODED AS 2632.3 FEET) TO QUARTER POST TO NORTH. THE 1 INCH PIPE WAS ERRONEOUSLY THOUGHT TO BE CORNER A-11 T3S, R17W AND IN FACT THE 1 INCH PIPE IS CORNER M-11, T3S, R18W.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 3/4 INCH PIPE ON TOWNSHIP LINE FROM ABOVE CORNER HISTORY AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

REPLACED 3/4 INCH PIPE WITH A BERRIEN COUNTY STANDARD BRASS CAP IN 36 INCH LONG CONCRETE MONUMENT WITH DRILL HOLE AND PS19618 STAMPED ON TOP.

THIS CORNER WAS RATIFIED BY THE BERRIEN COUNTY SURVEYOR'S PEER GROUP ON AUGUST 22,-2000

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SOUTHWEST CORNER OF SECTION 30, TOWN 3 SOUTH, RANGE 17 WEST. WITNESS TAG & NAIL IN WEST SIDE OF 14" OAK 030° 7.59 FEET WITNESS TAG & NAIL IN SOUTH SIDE OF 14" OAK AZ. 070° 9.54 FEET WITNESS TAG & NAIL IN EAST SIDE OF 17" SASSAFRASS 175° 7.00 FEET WITNESS TAG & NAIL IN SOUTH SIDE OF 6" SASSAFRASS 270° 3.65 FEET CORNER M-11, TOWN 3 SOUTH, RANGE 18 WEST 000° 19.80 FEET

Signed by August Surveyor's Michigan License No.

Survey & REMONUMENTATION

JAN 31 2001

209PAGE

SECTION

