RECORDED

DFFICIAL CORNER UNDER MICHIGA	N			
PUBLIC ACT 345 OF 1990	Rerrien Cou	nty Remonumentation	a u 20 2 r 2 P 1 1 9 5	
Jaco Jaken	LAND CORNE	R RECORDATION CERT	ILEICATE CONTRACTOR CO	
Q-22-95	Filing Require	ement of Act 74, Mich. F	The water recording	
For corners in		<b>,</b>	MEDITER OF DELIS MEDITER OF DELIS MEDITAL FORMAT MODERNAM	
Werrien (County)	Located In:	Corner Code ≠	A BARA PRIME MORE TO THE	
1. Public Land Survey	T <u>4S R 18W</u>	<u> </u>		
	T R T R			
	T R	******		
. ,	T R		11/29/95 111W2015 A6	
	T R T R		Register of Deeds Stamp & File Number	
	т R		STATE REPLANTED \$2.0	
4. Lot No, Recorded		•	A B C D E F G H I J K L M	
5. Private Claims			2 6 5 - 4 3 - 2 - 1 - 1	
		÷	3	
			4 7 8 9 10 11 12 12	
I. Daniel B. Zwar, in a field do hereby certify that under requirement	ild survey on <u>Novembe</u> is of P.A. 74, Michigan P.A.	of 1970, the corner points ment	tioned 6 18 17 16 15 14 13	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land				
Management or by a decree of a Court of	Law and/or that the corne	r points mentioned in lines 3, 4	and 5 8 19 20 21 22 23 24	
above were in conformance with the rule Court of Law; established, re-establi	es of the Michigan Board o shed, monumented, re-r	of Land Surveyors or by a Decre nonumented, recovered, fou	nd as	
expressed below:			10 30 29 28 27 26 25 2	
NOTE: Not more than 4 corners, a on this certificate.	all in the same town an	nd range, may be recorded	12 31 32 33 34 35 36-	
A. Description of original monume	nt and accessories and	d/or subsequent restoration	n:	
1827 Wm. Brookfield		1945 (from E.R. S	tefan library) Dewey?	
set corner post to 24 & 2	.5		Sec 24-4-18 Stone & Brick	
Beech 14 N71 W-9 Links Beech 8 S30 W-32 Links		B) SW corner of "A" is 76.8'	Sec 19-4-17 Plug	
beech b 550 " or =====		11 15 70.0	5045 01 -	
,		1972 R Garrett	SE corn sec 24-4-18	
		Stone with Brick		
		6" Hickory S5°W 2	1.9' Utility Pole N5°E 24.9' 4-17 N 76.8' stablishing corner:	
B. Description of corner evidence	found and/or method a	applied in restoring or rees	tablishing comer:	
November 13, 1995 found feet North to SW corner	pointed stone su of section 19-4-	rrounded by pieces 17, verified.	of red brick. Measured 76.84'	
			CONTRACT	
			LEARNINGN	
			MAR 2 7 1996	
		;	COMMISSION	
			le setting the againting of the accuse.	
C. Description of monument for co				
Witnessed point on stone, 3'X4" dia. concrete monum	ent and brass BO	CRP cap. Left Bric	ks surrounding monument.	
Corner is accepted as a	areful and faith	hful perpetuation o	of the position of the	
original corner.			WHATE OF MICHIGAN	
Witnesses: set nail w/washer in 12"	Maple N46°E 32	.851		
set nail w/washer in 6" h	Maple S 50 E 20.	.99'	ZWAR ZWAR	
set nail w/washer in 15" SW corner Section 19-4-11	Twin Ash S32°W	22.39'	DANIEL B. ZWAR PROFESSIONAL SURVEYOR	

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

POFESSION

3PAGE 318

Signed by .

Surveyor's Michigan License No. ....