

**SURVEY &
REMONUMENTATION**

12/29/93

111#5256 A66
CORNER \$7.00
111#5256 A66
STATE REMON FEE \$2.00

FEB 17 1994

**Berrien County Remonumentation Program
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

RECORDED

COMMISSION

For corners in

Berrien
(County)

Located In:

Corner Code #

DEC 29 3 19 PM '93

Berrien County
REGISTER OF DEEDS
REMONUMENTATION, MICHIGAN

- | | | |
|------------------------------------|--------------------------|-------------|
| 1. Public Land Survey | T <u>4S</u> R <u>19W</u> | <u>I-12</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

I, Charles W. Barger, in a field survey on _____, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
Iron in Monument Box

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1/2" iron rod in monument box over stone

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Replaced 1/2" iron rod with 1" iron pipe 1.1' long with 2-1/2" remonumentation brass cap over stone.
CB N41.5°E 51.9'
Manhole S32°W 27.8'
Manhole N59°W 28.1'
Manhole S42.5°E 38.8'



Signed by Charles W. Barger P.S.
Surveyor's Michigan License No. 31589

Date December 29, 1993