

SURVEY & REMONUMENTATION

12/29/93

111W5256 A66
CORNER \$7.00
111W5256 A66
STATE REMON FEE \$2.00

FEB 17 1994

COMMISSION

Berrien County Remonumentation
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

For corners in

Berrien (County)	Located In:	Corner Code =#
1. Public Land Survey	T <u>4S</u> R <u>19W</u>	<u>I-13</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

DEC 29 3 19 PM '93

Bernice J. ...
REGISTER OF DEEDS
BERRIEN COUNTY MICHIGAN

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Charles W. Barger, in a field survey on December 29, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:


- 1/2" iron rod in Monument Box
- SE corner of Brick building N80°W 94.7'
- SE corner of sign box N70°W 36.9'
- Power Pole #B230-145 S80°E 19.7'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Same as in paragraph A

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 0.7' long 1" iron pipe with 2-1/2" remonumentation brass cap placed around top of 1/2" iron rod.
- SE corner of planter N60°W 36.9'
- SE corner of building N72°W 94.7'
- Hydrant S52°W 116.3'
- Power Pole #B230-145 19.4 to "witness point" disc S69°E



Signed by Charles W. Barger P.S. Date December 29, 1993
Surveyor's Michigan License No. 31589