SURVEY PEER GROUP AS	S THE		* * in	
FFICIAL CORNER UNDER M DBLIQ ACT 345 OF 1	1000	ounty Remonumentation Progra	NIMA.	
Account	O(LAND CO	RNER RECORDATION CERTIFICA		-9 PM 12: 51
8-22-05 Filing Re	quirement of Act 74, Mich.	P.A. 1970	มน์ได้เสีย อาการเก	E TRETHEWAY
For corners in			JERRIEN C	TER OF DEEDS COUNTY, MICHIGAN
V Berrien	Located In:	Corner Code #		
(County)			11/08/00	111#6048 A66
1. Public Land Survey	T 58 R 17W	<u>B-1</u>	11/08/00	CORNER \$7.00 111#6048 A66
	T R T R			STATE REMON FEE \$2.00
	TR			
2. Property Controlling in Section	S T R		Parlata	
3. Miscellaneous	S T R S T R		Number	of Deeds Stamp & File
Property in Sec.	S			
4 lothio Don	and ad Dlack			
5. Private Claims	orded Plat		A B C D	E F G H I J K L M
•		,	2 6 5-	4 3 2 1
I, <u>Alan K. Bartlett</u>	, in a field survey on	March 29, 2000	3	
do hereby state that under	requirements of P.A. 74, Michiga lines 1 and 2 above were in a	4 - 7 - 8 -	9-10-11-12	
regulations and rules theref	ore as required in the current rates Department of the Interior	5	15-14-13	
Management or by a decre	e of a Court of Law and /or tha	t the comer points	7	
	5 above were in conformance w Surveyors or by a Decree of		8	21 2 2 3 24
established, re-established, below:	monumented, recovered, fou	and as expressed	10-20-0	
			1 30 29	28 27 26 25
NOTE: Not more than 2 on this certificate.	corners, all in the same town o	and range, may be recorded	12 31 32	33 34 35 36
	•	and/or subsequent restoration:	**	
		·		
	URVEYOR; SET CORNER FOR 1/A NKS WEST OF ABOVE NAMED C	POST ON NORTH SIDE OF SID ORNER AS PER FIELD NOTES, WITNE	SSES: S60°E 51 LINK	KS 6" SUGAR, \$30°W 52 LINKS
		GINEERING; 1/2 MILE SOUTH TO CEN GINEERING; 1/2 MILE EAST TO C-1 = 2		
S45°W 19.14' 8" H	ICKORY, N5°W 3.65' 8" TREE	-		,
	IGHTMAN & ASSOCIATES; IRO1	ERING; ½ MILE EAST TO C-1 =2615.3 N PIPE AND STONE, WITNESSES: S50°		\$45°W 19.14' 8" HICKORY,
B. Description of corner	evidence found and/or meth	nod applied in restoring or reestab	lishing corner:	
	TONE, BOTH 1' ABOVE GROUN	ID. DNUMENTATION PEER GROUP OF SI	IRVEYORS	
3311,2111				
C. Description of monun	ment for corner and accessori	es established to perpetuate loca	ling the position o	f the corner:
	WITH BRASS CAP (MARKED 2000 & ED BY ORIGINAL GOVERNMENTS	35988). URVEYORS, THIS MONUMENT IS ACCEP	TED AS THE BEST AVA	AILABLE EVIDENCE OF THE
POSITION OF THE CORNER.				A CONTRACTOR OF THE PARTY OF TH
				Service Control
	NORTH 3.67' 14" ASPEN N38°E 38.02' 20" POPLAR			ALAN TO
	SOUTH 16.21' 8" ASH		.	BARTLETT
	S50°W 19.09' 20" ASH WEST 28.76' 12" ASH		₹.	SURVEYOR No.
	EAST 8.91' B-13- \$ 1/4 SECTIO	N 31- REMONÚMENTED	*	35988
Sanadby A	KR TOH	Data	11/02/20	CAND SU
Signed by	1. June	Date	102/20	
Surveyor's Michigan Licen	se No. 35988			
SURVEY		FORM APPROVED BY #	LICHIGAN STATE BOARD OF	F PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975
REMONUMEN	IAHON		•	REVISED JAN., 1983

PAGE 241

LIBER f 4

SECTION

JAN 3 1 2001