RATIFIED BY THE BERRIEN COUNTY
SURVEY PEER GROUP AS THE

RECORDED

DEFICIAL CORNER UNDER MICHIGAN
PUBLIC ACT 345 OF 1990
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

98 NOV 19 PM 4: 67

BERNICE TRETHEWAY REGISTER OF DEEDS BERRIEN COUNTY, MICHIGAN

111#/100

111#6180

CORNER

A77

\$9.00

For corners in BERRIEN COUNTY	Located PIPESTON			er Code # 1 POST SEC 25	
 Public Land Survey Property Controlling Section Miscellaneous Property in Sec. 	-	T 5S T T T T T T T T T	R_17W R R R R R R R	<u>M-10</u>	
4. Lot NoRec 5. Private Claims	corded Plat				

I, <u>Alan Bartlett</u> in a field survey on <u>November 13 1998</u> hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

STATE REMON FEE \$2.00 κ F В C D 10 12 ß 15 7 20 22 24 9 25 10 29 30

Register of Deeds Stamp & File Number

11/17/78

11/19/98

CUTATE S. REMONONERATION

JAN 12 1999

A. Description of original monument and accessories and/or subsequent restoration:

SECTION

(Please see back page)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Bent Rebar 6' West of Center Line of Brush Lake Road. Verified Corner using existing witnesses. This Government Monument was restored with approval of the Berrien County Remonumentation Peer Group of Surveyors October 6 1998.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3' Steel Pipe with 3" dia Berrien County Remonumentation Cap and Monument Box 6' West of Center Line of Brush Lake Road.

Witnesses
N35W Center Line Phone Riser
S45E Set Nail & Flasher in SW side of Power Pole
S30W Set Nail and Flasher in E face of 18" Quad Trunk tree
South Found Iron Pipe in Mon. Box
East S edge Steel Post for Stop Sign

30.20'
117.16'
67.40'
14.95'
66.54'

Corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by No. 35988
Surveyor's Michigan License No. 35988

Date ///16/98



M-10 E 1/4 CORNER SECTION 25 T5S, R17W PIPESTONE TWP.

March 1827 GLO William Brookfield Book 1 Page 108 of Field Notes

North on East Side of Sec 25

40.00 1/2 Mile Post

Witnesses

W. Oak 9 S65 3/4 W 23 lks "do" 26 N51/2W 47 lks

BCRC no dates

Stone

Witnesses

18" W.Oak N63W 53.6' 18" Y. Oak S33W 52.0' Tel Pole N65E 35.3'

Jog 14.5' to W1/4 Post Sec 30 Pokagon Twp. Cass County

J.H. Dewey

March 1992

(Misc. Field Notes)

Stone

Witnesses (Same as BCRC)

Sept 1979 Wightman and Assoc. M.R. Rushlow #15191 Recorded Survey Liber1121, Page 423

ron

Witnesses

| Iron Pipe | South | 15.28' | Telephone Riser Box | N45W | 30.76 | C/L Road | East | 6' | 2633.34' S0 38' 16"E to S.E. Corner Sec 25-5-17

Robert Prestine Survey Certificate

Jog info; 15.1' South to W1/4 Cor Sec 30 fnd 3/4" Pipe

1998 Landmark Technologies Alan Bartlett RLS#35988

Found Bent Rebar 6' W of Center Line Brush Lake Road Witnesses

N35W Top Center Line of Phone Riser 30.20'
S30W Set Nail and Flasher in E face of 18" Quad Tree 67.40'
South Fnd I.P. in Monument Box 14.95'
East S. Edge Steel Post for Stop Sign 66.54'
S45E Set Nail and Flasher in SW side P.P. 117.16'

SUPPLY A REMONUNCIATION

JAN L 2 ₁₈₈₉

SECTION

LIBER