12/03/93

111#3384

A33

CURNER

\$7.00 A33

FEB 1 7 1994

12/03/93 111#3384 STATE REMON FEE \$2.00

Fo	COMMIST	OM	Filing Requi	ER RECORDATION CEI rement of Act 74, Mich. RIEN COUNTY REMONIMENT.	. P.A. 1970		REGISTER OF B			2 0	
	Berrien	Loc	ated In;	Corner Code =##			355 I	₹ .		273	
	(County)			Co-			議論	S -	-	CORD	
1.	Public Land Survey	T . T .	6S R 19W 6S R 19W R R	<u>(e1)</u> D1			Scaso Scaso	1 24 PM '93		DED	
2.	Property Controlling in Section	S T	R R			-					
3.	Miscellaneous	S T	_								
	Property in Sec.	S T	R		Hegis	ster of i	Deeds &	Stamp & I	-ile Nu	ımber	
							СБ	E	ні	1 6	
5.	Private Claims						1 1		" i	ŤŤ	Ť
						2 - 6-	 	1-4-1-	3——	-2	· į
		•			•	3	╁╾╁╌		 	+	\dagger
•	John G. Kamon		. Dogge		0.7	4 - 7-	- ß	ė –	10-	11-	-12
i, _ do				ber 2 . 19 , 19 , 19 of 1970, the corner points me		5	++-		1	+	+
in I	ines 1 and 2 above were	in conformance v	with regulations ar	nd rules therefore as require	d in the	5 18	- 1'7	16	15	-1'4	-13 1
				tment of the Interior, Bureau er points mentioned in lines 3,		7	++	 	 	 	†
				of Land Surveyors or by a Dec		8 19	 2'0	21-	22	23	24
Co	urt of Law; established.			monumented, recovered, fo	ound as	9	 	 	 	++-	+
·	ressed below:		0,			10 - 30-	29-	-2'8-	27	5,6	25
NO			he same town a	nd range, may be recorde		''	++-	 	+	╁╌╁╾	+
	on this certificat	e. .				12 -31-	32	-33-	34	35	36
A. c1	over stone. Acc over stone NW 79.70', 24" Oak box. Accessori North. Not set by gove Accessories: 10 1965 BCRC set M	essories: 14" Cor Hse SE 79. N 80° W 55.20° Les: Guard post rnment surveyo " Tulip S 37.2 on. box. 1979 4.86°. 1988 J	oak S 88° E 27. 2', 12" Maple ', 14" Maple S; S 25° E 35.85 rs. 1950 JH D ', 10" Tulip S M. R. Rushlow ohn G. Kamer 3	d/or subsequent restoration aims East of SW Cor Set 4', NW Cor House SE 79 NE 72.4', ECRC 1965 Se 70° E 66.95'. May 11, ', 20" oak west 56.12', ewey & BCRC iron & stor 70° E 40.6', 8" Elm NW Mon. Box, Tele Riser 5/4" rod. accessories; 1	.4', 12" Map t Mon. Box. 1988 John G , 8" oak S 2 nes 85' jog , 41.8', 10" S 31° R 33.2'	Acces Kame: 5° W 72 West to oak NE	or 72. sories r found .33', so S-1/4 90.1' Twin o	4'. 196; NW Cor 1 1/2" p: C _L Thorn 1 32-5-19 , 12" oa ak N 30°	2 W&A Hse S ipe in con Dr k NW 33.	I P 32 1 Mon. 14' 75'. 52',	r
B.	Description of corner	evidence found	and/or method a	applied in restoring or ree	stablishing co	orner:					
C1	Found 3/4' Rod consistent.	in Mon Box, SN	7 Cor 32-5-19 W	est 121.08', Distances	to adjacent	corne	rs were	e reason	able a	ınd	
D1	Found 3/4" Rod consistent.	in Mon Box, S	1/4 Sec 32-5-1	9 West 84.87'. Distan	ces to adjac	ent co	mers v	were rea	M/C/	o and	
				established to perpetuate			A RECOUNT	KA LANDS	IN G. MER JRVEY! No. 449	IR SOLUTION	- 111012 BARRELLE
C.	Description of monum	ient for corner a	nd accessories e	established to perpetuate	locating the p	osition	of the	corne D	WAND.	1199	
	C1 - Set 3' sta Mon. box and is	ndard pipe w/b	rass plate in careful and	D1 - This posi surveyors. Th	tion not est	tablish	ed by	original	gove:	rnment	

Mon. box and is accepted as a careful and faithful perpetuation of the original corner. Set Nail w/Witness Tag in 26" Oak N 82° W 56.03'
Set Nail w/Witness Tag in PP S 24° W 89.81'
Set Nail w/Witness Tag in Wood Post S 30° B 35.32'
NE Cor Hse at Block Foundation S 42° E 73.65'
SW Cor 32-5-19 Brass Plate in Mon. Box West 121.08'

surveyors. This monument is accepted as the best available evidence of this corner.

Set 3' standard pipe w/Brass Plate in Mon. Box

3' Standard pipe w/brass plate (S-1/4 Cor 32-5-19)

West 84.87'

1" Plumber IP ON Conc. headwall S 67° W 42.65'

Top of Hyd S80° W 73.22'

Found Nail w/Tag S3° R 35.84'

Signed by	•	Date	//
Supravar a Michigan Licenses No. 27419			

<u>z-0z-93</u>

65