FICUAL CORNER UNDER MICHIGAN PUBLIC ACT 345 01-3980 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 ERRIEN Located In: Corner Code ## T R 19 F-I T R 10/31/97 111#2484 Register of Deeds Skarip & Eleit Property in Sec. S T R 10/31/97 111#2484 Lot No. Recorded Plat S. Private Claims Private Claims CHARLES W. BARGER in a fleid survey on OCTOBER 19 F- A 11970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Count of Law and/or hat the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Count of Law and/or hat the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Count of Law and/or hat the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Count of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration:	A9
1. Public Land Survey T 7 R 19 F-1 T R T R T R T R T R T R T R T	
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R 4. Lot No, Recorded Plat	
in Section S T R R 10/31/97 111#2484 3. Miscellaneous S T R R Register of Deeds Starrip & Elicit 4. Lot No. Recorded Plat	\$9.0
4. Lot No, Recorded Plat	A9
4. Lot No, Recorded Plat	umbe#2.0
1. CHARLES W. BARGER in a field survey on OCTOBER 19 97 of the hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	
	J K L
L. LYON 1830 REMONUMENTATIO NOV 2 1 1997 COMMISSION	-3536-

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C. BARGER

1997

5/8" REBAR IN MONUMENT BOX

54.44 SAN MH N83DEG20'W

WATER MH N17DEG29'W 48.4'

P.K. IN PP S60DEG27'E 57.27' 5/8" REBAR IN MON W 40.88'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" PIPE 36" LONG WITH 21" REMONUMENTATION BRASS CAP IN MONUMENT BOX

SAN MANHOLE

N83DEG20'W

54.44'

WATER MANHOLE

N17DEG29'W

48.41

WITNESS TAG IN PP S60DEG27'E

57.27

2½" REMONMENT MARKER OVER 1" PIPE W 40.88"

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE

POSITION OF THE ORIGINAL CORNER.

Surveyor's Michigan License No. 31589

Date <u>OCTOBER 31, 1997</u>

BARGER ENGINEERING, INC. BERRIEN COUNTY REMONUMENTATION

NORTH QUARTER POST SECTION 4, TOWNSHIP 7 SOUTH, RANGE 19 WEST (F-1) DATE ROAD

L. Lyon 1830

Berrien County Road Commission 1920-45	Stone & Plow Point 30" Maple S 12" Hickory N15degE 30" Oak N20degw Fence S	35.2' 36.3' 74.0' 23.7'
C. Barger 1997	5/8" Rebar in Monument San MH N83deg20' Water MH N17deg29' P.K. in PP S60deg27'	W 54.44' W 48.4' E 57.27'

REMONUMENTATIO

NOV 2 1 1997

COMMISSION

JOB ASSIGNMENT 1997-02-0294