Surveyor's Michigan License No. 22436

FEB 17 1994

	DEC 28 2 17 PM 93 BERRIEN COM	MAN A SA MANDA EN LY LT	ווא אסטאא אטט				
		RNER RECORDATION	CERTIFICATE _{12/2}	8/93	111#5115	022	
For	Filing Requirement of Act 74, Mich. P.A. 1970				Charters (people	A33	
	Berilenna of Hillos Berilenna in:	0			CURNER	\$7.00	
	(County)	Corner Code ##	12/2	8/93	111#5115 STATE REXON	A33 FFF 42 NO	
_	Direction 10 and T. a. D. 40				DIFFEE NUMBER	TLL FL. OU	
1.	Public Land Survey T_8 R T R						
	T R						
	T R			•			
2.	Property Controlling S T R						
•	in Section S T R						
3.	3. Miscellaneous S T R						
riopesty in dec.							
4.	Lot No, Recorded Plat			BCD	EFGHI,	I K I M	
5.	Private Claims		······································				
			3	— 6-—— 5 !	1 1 1	2 - 1 - 1	
			4				
ι, _	R.L. Harner , in a field survey on Nove	mber 11	93 5	1 1		112	
do	do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned						
	in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land						
Mai	Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5						
	ve were in conformance with the rules of the Michigan Boa irt of Law; established, re-established, monumented,				 		
	ressed below:	,	10	-30 -29	28 27 2	25	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded					 		
	on this certificate.		12	—3 ¹ 1——3 ¹ 2—	3/3 3/4	36	
A.	Description of original monument and accessories	and/or subsequent resto	13 L pration:	<u></u>	 	 	
	0.0	u o		•			
	<u>H-9</u> No record					ad	
		Commission - n		551115	ii dddiidy iid		
Fence post East 16.2 ft. Fence post West 16.1 ft. 12" oak N.W. 40.0 ft. Iron - R.W. Prestine Aug. 1977 Center 36" oak N. 22° W. 40.3 ft.							
E'ly corner brick wall West 32.7 ft. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:							
p. Description of corner evidence found and/or method applied in restoring or reestablishing corner;							
	<u>G-9</u> <u>H-9</u>						
	Found stone - recently used by othe	rs Found 3/4"	iron				
		•					
C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner:						
		The street of polyotte	and house the boo	on or the	oution,		
	<u>G-9</u> Removed stone - set concrete monume	nt <u>H-9</u>			`		
	with brass cap	Set	concrete monum		·		
	P.K. nail in 12" maple N. 35° E.	23.30 16.	P.K. nail in P.P. West 29.53 ft. P.K. nail in 40" oak N. 22° W. 39.73 ft.				
	P.K. Nail in twin ash N. 10° E. 8.	10 1t.	corner of bri				
	P.K. nail in 20" maple S. 40° W. P.K. nail in 12" maple S. 65° E.	13.42 16.	nail in R.R.				
	L.V. Harr In 15 Habra 3. no c.	21010 60					

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Bevised May 14, 1975 Revised Jan., 1983

Date <u>December 28, 1993</u>