SURVEY & REMONUMENTATION

FEB 1 3 2001

SECTION

For corners in

expressed below:

BRANCH COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Fili

ng Require	STATE OF TH	
in:	Corner Code ##	09-26-2000

ICHIGAN nty.

BRANCH (County) GIRARD TWP•	Located In:	Corner Code ≠	09-26-2000 10:17:23
Public Land Survey	T <u>5 S R 6 W</u> T R T R	<u> </u>	Linda Lee Morrison-Mathews REGISTER OF DEEDS
Property Controlling in Section	T R S T R S T R		Liber 00004 Page 0101
 Miscellaneous Property in Sec. 	S T R S T R		Register of Deeds Stamp & File Number
	Recorded Plat		GIRARD TWP., T5S, R6W ABCDEFGHIJKLA
3. The Claims		-	3 3 2 1 -
do hereby certify that under re-	Sin a field survey on MAY 3 quirements of P.A. 74, Michigan P.A. oconformance with regulations an	of 1970, the corner points mentio	ioned 6 1 1 1 1 1

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

A. Description of original monument and accessories and/or subsequent restoration: TION CORNER, SEC'S. 5-6-7-8-, T5S, R6W.

1825; G.L.O. FIELDNOTES OF ROBT. CLARK, JR., D.S. - "80.00 SET POST COR SEC'S 5,6,7 & 8".

1890: SURVEY BY J.H. BENNETT - "SEC. CORNER. FOUND STAKES & STONE BUT NO TRACES OF U.S. TREES. CORNER WELL PRESERVED." (WINTESS NOW GONE)

12 13

1874: SURVEY BY M. KNOWLES, CO. SURVEYOR - (NO INFORMATION GIVEN FOR THIS CORNER).

1938: SURVEY BY R. V. TERRILL, REGISTERED SURVEYOR - "FOUND TWO STONES TOGETHER, BROKEN BRICK, OLD STOYE LEG AND 8" TAPERED END OF AUTO AXLE. IN CENTER OF ROAD AND IN LINE WITH FENCES NORTH & SOUTH. (HIS THREE WITNESSES ARE NOW GONE).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

DUG AND FOUND THE TWO STONES WITH OLD AXLE SHAFT BETWEEN THE STONES. I SET A BRANCH COUNTY REMONUMENTATION CAP ON 1/2"x24" REBAR BETWEEN THE TWO STONES & PLACED THE AXLE SHAFT BESIDE THE REBAR. PLACED A C-I MONUMENT BOX COVER (UNABLE TO SET A BOX) OVER THE REMON. CAP.

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

BRANCH COUNTY REMONUMENTATION CAP ON REBAR, BETWEEN STONES, UNDER C-I MONUMENT BOX COVER:

NORTH 45 EAST 56.90' - NEAR FACE OF POWER POLE.

DUE SOUTH 37.50' - FACE OF 2" DIA. STEEL ANCHOR POST, WITH FENCELINE RNG. SOUTH

SOUTH 22 EAST 39.31' - CENTER OF 12" ASH TREE.

SOUTH 42 WEST 55.75' - CENTER OF 12" ASH TREE.

ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 MEETING HELD

> Zeed. R. REED, Co. Rep.

Signed by .

Surveyor's Michigan License No. 7437

EDWARD R. REED ROFESSIONAL SURVEYOR PERMORE)

Date MAY 3, 2000