SURVEY & REMONUMENTATION

MAR 2 1 1997

BRANCH COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE OF MICHIGAN Filing Requirement of Act 74, Mich. P.A. 1970 ranch County

For corners COMMISSION	Filing Require	ement of Act 74, Mich. P.	
BRANCH	Located In:	Corner Code ##	Recorded
(County)			10-30-1996 09:20:27
GIRARD TWP. 1. Public Land Survey	т <u>5S</u> я <u>6W</u>	E-12	Linda Lee Morrison—Mathews
	T R		REGISTER OF DEEDS
•	T A T A		
	T R		Liber 00003 Page 0078
	T R T R		·
	T R		Register of Deeds Stamp & File Number
4. Lot No, Record			A B C D E F G H I J K L M
, 1 mail of officers	·		2 6 6 6 6 6 7 5 7 5 7 5 7 5 7 5 7 5 7 5 7
			3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
, EDWARD W. REED , in a	field survey onSEPTE	MBER 4 19 _96_	5 7 8 9 10 11 12
to hereby certify that under requirement lines 1 and 2 above were in confo	ents of P.A. 74, Michigan P.A.	of 1970, the corner points mentio	oned 6 18 17 16 15 14 13
current manual of survey instructions	of the United States Depart	ment of the Interior, Bureau of L	Land 7
Management or by a decree of a Court bove were in conformance with the ru			
Court of Law; established, re-establexpressed below:	lished, monumented, re-m	nonumented, recovered, found	t as
IOTE: Not more than 4 corners	, all in the same town an	d range, may be recorded	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
on this certificate.	,		12 31 32 33 34 35 36
A. Description of original monum	ent and accessories and	l/or subsequent restoration:	13
QUARTER CORNER COMMON T	O SECTIONS 32, & .	33, T5S, R6W, GIRARD	TWP, BRANCH COUNTY, MI
1825: ROBERT CLARK, JR			S POST SET DEEP IN GROUND
WITH BRICK & IRO		מאוזעמאט ום מחואאייו	D FOOT BILL THE GROOME
· · · · · · · · · · · · · · · · ·		TLE IN STONE WITH ST	AKE IN CENTER, PLACED 3/4" GAS
PIPE IN PLACE OR 1973: E.R. REED, COUNT		3/4" IRON PIPE, REO	ORDED L.C.R.C. #065
•			
. Description of corner evidence		pplied in restoring or reesta	blishing corner:
FOUND 1/2" IRON INSIDE	-		
SET REMONUMENTATION CAP SET CAST IRON BOX FLUSH		E	
	٠		ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345
			OF 1990 AT A MEETING HELD ON
			F.R. Red On Ree.
			E.R.REED
Description of monument for o	-arear and naconnarios a	stablished to perpetuate 100	eating the position of the corner:
1/2" IRON WITH REMONUME			A CONTRACTOR OF THE PARTY OF TH
E 30.9'-ANGLE IRON ANCH		51 11011 2021	EDMARD.
W33.3' TO NE CORNER OF			TOWARD A S
S70E 26.1' TO NAIL IN T N33W 59.0' TO SW CORNER			W. REED *** LAND ***
N83W 44.0' TO 12" ASH			SURVEYOR
N58E 56.8'TO SW CORNER		NING WALL	NO.
N20W 70.0' TO FACE OF P S20W 87.0' TO FACE OF P			SED LAND SURVEY
			OFO LAND SUR
AND IS ASCEPTED AS A	CAREFUL AND FAITH	FUL PERPETUATION OF	THE POSITION OF THE ORIGINAL CORNER.
igned by Calmi A	1). / ref	Date	SEPTEMBER 4, 1996
igned by <u>EDWARD W. REED</u> urveyor's Michigan License No			FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
urveyor s iviichigan Eidense 140. L			FORM APPROVED BY MICHIGAN STATE BUARD OF EACH SERVISED MAY 14, 1975