SURVEY & REMONUMENTATION

FEB 0 3 1999

SECTION

BRANCH COUNTY REMONUMATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			
			STATE OF MICHIGAN
BRANCH COUNTY	Located In:	Corner Code #	Branch County
GIRARD TWP			Recorded
1. Public Land Survey	T <u>58 R6W</u>	_J-7	11-04-1998 15:47:55
	T R		
	T R		Linda Lee Morrison-Mathews REGISTER OF DEEDS
2. Property Controlling	TR S T R		
in Section	S		Register of Deeds Stamp & File Number
	T R	ACCEPTED BY	THE BRANCH COUNTY
3. Miscellaneous	\$ T R	SURVEY PEER G CORNER UNDER M	ROUP AS THE OFFICIAL
Property in Sec.	I K	OF 9 1990 AT 9	MEETING HELD ON
rioperty in occi	T R	ER.	Reed. Co. Ress.
			R.REED
4 1 . 31 . 19	None and all miles	_	- · · · · · · · · · · · · · · · · · · ·
4. Lot No , F	Recorded Plat		ABCDEFGHIJKL
5. Private Claims			2 6 5 4 5 1 - 3
			3
			4 - 7 - 3 - 9 - 10 - 11 - 12
I. EDWARD W. REED	in a field survey onAUG	JST 25 . 19 98 do hereby	5
1, <u>EDWARD W. REED</u> , in a field survey on <u>AUGUST 25</u> , 19 <u>98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in			6 19 17 16 15 14 13
	conformance with regulations and tructions of the United States Depa		7
Land Management or by a d	ecree of a Court of Law and /or the	at the corner points mentioned in	8 19 20 21 22 23 24
	ere in conformance with the rules a Court of Law; established, re-esta		9 10 30 29 28 27 26 25
found as expressed below:			11
NOTE: Not more than 2 co	omers, all in the same town and rang	ge, may be recorded	12 31 32 33 34 35 36
on this certificate.			13
QUARTER CORNER COM	MON TO SECTIONS 14 & 23		
	MON TO SECTIONS 14 & 23 I monument and accessories and	d/or subsequent restoration:	
A. Description of origina	I monument and accessories and	d/or subsequent restoration:	
	I monument and accessories and	d/or subsequent restoration:	
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC	I monument and accessories and		shing corner:
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner	I monument and accessories and D.S CORNER SET DN PIPE, WITNESS evidence found and/or method	applied in restoring or reestablis	shing corner:
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner CORNER NOW GONE V	I monument and accessories and D.S CORNER SET DN PIPE, WITNESS	applied in restoring or reestablis	shing corner:
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner CORNER NOW GONE V RESET CORNER FROM	I monument and accessories and D.S CORNER SET DN PIPE, WITNESS evidence found and/or method VITH BRIDGE REPLACEMENT SURVEY NOTES OF MSHD	applied in restoring or reestablis	shing corner: ate locating the position of the corner:
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner CORNER NOW GONE V RESET CORNER FROM C. Description of mo	I monument and accessories and D.S CORNER SET DN PIPE, WITNESS evidence found and/or method VITH BRIDGE REPLACEMENT SURVEY NOTES OF MSHD	applied in restoring or reestablis sories established to perpetu	ate locating the position of the corner:
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner CORNER NOW GONE V RESET CORNER FROM C. Description of mo	I monument and accessories and D.S CORNER SET DN PIPE, WITNESS evidence found and/or method WITH BRIDGE REPLACEMENT SURVEY NOTES OF MSHD onument for corner and acces	applied in restoring or reestablis sories established to perpetu P IN CI-MONUMENT BOX FL	ate locating the position of the corner: USH WITH PAVED ROAD SURFACE
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner CORNER NOW GONE V RESET CORNER FROM C. Description of mo SET ½" X 18" REBAR II 10" POPPLE TEL POLE	I monument and accessories and D.S CORNER SET ON PIPE, WITNESS evidence found and/or method WITH BRIDGE REPLACEMENT SURVEY NOTES OF MSHD onument for corner and access IRON ROD WITH REMON CANORTH 25.7' TO CENTIS 42 W 34.2' TO FACE	applied in restoring or reestablis sories established to perpetu P IN CI-MONUMENT BOX FL	ate locating the position of the corner: USH WITH PAVED ROAD SURFACE EDWARD
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner CORNER NOW GONE V RESET CORNER FROM C. Description of mo SET ½" X 18" REBAR II 10" POPPLE TEL POLE GUARD RAIL POST	I monument and accessories accessories and accessories and accessories accessories and accessories accessories and accessories accessories accessories accessories accessories and accessories	applied in restoring or reestablis sories established to perpetu P IN CI-MONUMENT BOX FL	ate locating the position of the corner: USH WITH PAVED ROAD SURFACE
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner CORNER NOW GONE V RESET CORNER FROM C. Description of mo SET ½" X 18" REBAR II 10" POPPLE TEL POLE GUARD RAIL POST	I monument and accessories and p.S CORNER SET ON PIPE, WITNESS evidence found and/or method WITH BRIDGE REPLACEMENT SURVEY NOTES OF MSHD onument for corner and access IRON ROD WITH REMON CANORTH 25.7' TO CENTILS 42 W 34.2' TO FACE N 32 E 15.4' TO FACE	applied in restoring or reestablis sories established to perpetu P IN CI-MONUMENT BOX FL	ate locating the position of the corner: USH WITH PAVED ROAD SURFACE EDWARD W. REED LAND SURVEYOR
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner CORNER NOW GONE V RESET CORNER FROM C. Description of mo SET ½" X 18" REBAR I 10" POPPLE TEL POLE GUARD RAIL POST GUARD RAIL POST	I monument and accessories accessories and accessories and accessories accessories and accessories accessories and accessories accessories accessories accessories accessories and accessories	applied in restoring or reestablis sories established to perpetu P IN CI-MONUMENT BOX FL	ate locating the position of the corner: USH WITH PAVED ROAD SURFACE EDWARD W. REED LAND SURVEYOR NO.
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner CORNER NOW GONE V RESET CORNER FROM C. Description of mo SET ½" X 18" REBAR I 10" POPPLE TEL POLE GUARD RAIL POST GUARD RAIL POST AND IS ACCEPTED AS	I monument and accessories and D.S CORNER SET ON PIPE, WITNESS evidence found and/or method WITH BRIDGE REPLACEMENT SURVEY NOTES OF MSHD onument for corner and access IRON ROD WITH REMON CANORTH 25.7' TO CENTIS 42 W 34.2' TO FACE N 32 E 15.4' TO FACE S 46 E 26.8'	applied in restoring or reestablis sories established to perpetu P IN CI-MONUMENT BOX FL	ate locating the position of the corner: USH WITH PAVED ROAD SURFACE EDWARD W. REED LAND SURVEYOR NO. 33985
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner CORNER NOW GONE V RESET CORNER FROM C. Description of mo SET ½" X 18" REBAR II 10" POPPLE TEL POLE GUARD RAIL POST GUARD RAIL POST AND IS ACCEPTED AS OF THE POSITION OF T	I monument and accessories and D.S CORNER SET ON PIPE, WITNESS evidence found and/or method WITH BRIDGE REPLACEMENT SURVEY NOTES OF MSHD onument for corner and access IRON ROD WITH REMON CANORTH 25.7' TO CENTIS 42 W 34.2' TO FACE N 32 E 15.4' TO FACE S 46 E 26.8' A CAREFUL AND FAITHFUL THE ORIGINAL CORNER.	applied in restoring or reestablis sories established to perpetu P IN CI-MONUMENT BOX FL	EDWARD W. REED LAND SURVEYOR NO.
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner CORNER NOW GONE V RESET CORNER FROM C. Description of mo SET ½" X 18" REBAR II 10" POPPLE TEL POLE GUARD RAIL POST GUARD RAIL POST AND IS ACCEPTED AS OF THE POSITION OF T	I monument and accessories and D.S CORNER SET ON PIPE, WITNESS evidence found and/or method WITH BRIDGE REPLACEMENT SURVEY NOTES OF MSHD onument for corner and access IRON ROD WITH REMON CANORTH 25.7' TO CENTIS 42 W 34.2' TO FACE N 32 E 15.4' TO FACE S 46 E 26.8' A CAREFUL AND FAITHFUL THE ORIGINAL CORNER.	applied in restoring or reestablis sories established to perpetu P IN CI-MONUMENT BOX FL	ate locating the position of the corner: USH WITH PAVED ROAD SURFACE EDWARD W. REED LAND SURVEYOR NO. 33985
A. Description of origina 1825: R. CLARK, JR, D 1963: MSHD - 3/4" IRC B. Description of corner CORNER NOW GONE V RESET CORNER FROM C. Description of mo SET ½" X 18" REBAR II 10" POPPLE TEL POLE GUARD RAIL POST GUARD RAIL POST AND IS ACCEPTED AS OF THE POSITION OF T	I monument and accessories and D.S CORNER SET ON PIPE, WITNESS evidence found and/or method WITH BRIDGE REPLACEMENT SURVEY NOTES OF MSHD onument for corner and access IRON ROD WITH REMON CANORTH 25.7' TO CENTIS 42 W 34.2' TO FACE N 32 E 15.4' TO FACE S 46 E 26.8' A CAREFUL AND FAITHFULTHE ORIGINAL CORNER.	applied in restoring or reestablis sories established to perpetu P IN CI-MONUMENT BOX FL	EDWARD W. REED LAND SURVEYOR NO. 33985