SURVEY & REMONUMENTATION

FEB 1 3 2001

BRANCH COUNTY REMONUMENTATION PROGRAM

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 STATE OF MICHIGAN

,				Branch County Recorded	ii r
For corners in				12-15-2000 14:06	£51
BRANCH COUNTY GIRARD TWP	_ Located In:	Corner Cod	e #	Linda Lee Morris	on-Mathews
1. Public Land Survey	T <u>5S</u> R <u>6</u> TR			REGISTER OF DEED	S
	T R T R			Liber QQQQ4 P	0123
Property Controlling in Section	S R S			Register of Deeds Sta	mp & File Number
3. Miscellaneous	T R S			BY THE BRANCH COUNT ER GROUP AS THE OFFICIA	L
Property in Sec.	T R S		CORNER UND OF 1990 //- 28-	AT A MEETING HELD OF	Ň.
	T R		<u>-</u>	E.R. REED, CO.T.	i Pep
4. Lot No, Rec	orded Plat			A B C D E F G	8 1 J K L M
5. Private Claims				2 6 5 4	-3-2-1-
I, <u>EDWARD W. REED</u> , ir requirements of P.A. 74, Michi	igan P.A. of 1970, the c	corner points mentioned in	lines 1 and 2	3 4 7 8 9	_101112
above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 6 18 17 16 15 14 13					
3, 4 and 5 above were in confo or by a Decree of a Court of L	ormance with the rules o	f the Michigan Board of La	and Surveyors	6 -18 17 -16 7	15 14 15
as expressed below:				8 19 20 21	22 23 24
NOTE: Not more than 2 come on this certificate.	rs, all in the same town a	and range, may be recorde	d	10 30 29 28	-272625
QUARTER CORNER OF SEC	TIONS 24 AND 25, (i GIRARD TOWNSHIP, BI	RANCH	11 31 32 33	-34 -35 -36-
A. Description of original m	 nonument and access	ories and/or subsequen	nt .	13	
restoration: 1825: R. CLARK, JRCORN	•		•		
1865: A.R. DAY-STONE AN 1901: HAMILTON-STONE V	ND BRICK	ES AGREFING: N & S			
B. Description of corner ev		1.1	ring or reestabl	ishing corner:	
FENCELINES NOW GONE AT POINT ON LINE AND MIDWAY BETWEEN CORNERS EAST AND WEST					
UNABLE TO LOCATE ANY EVIDENCE OF CORNER POINT FALLS ON LINE BETWEEN RAILROAD POST-600 + /- SOUTH AND WOOD PST 250 + /- NORTH					
SET POINT ON LINE AND M SET ½" X 18" REBAR IRON	IIDWAY BETWEEN SI	ECTION CORNER EAST	AND WEST		O SURFACE
C. Description of monument	t for corner and acces	ssories established to p	erpetuate locat	ing the position of the o	corner:
SET ½" X 18" REBAR IRON			ATION BOX FLU	ISH WITH PAVED ROAL	SURFACE
CENTERLINE ROAD 4" BIRCH	i 1	SOUTH 4.0' N18E 31.8'		0 = 01 = 1	
3" MAPLE SW CORNER OF HOUSE AD		\$33E 47.3' N56E 126'		M. REED 1	
SW CORNER BARN		N8E 169'		LAND SURVEYOR	
AND IS ACCEPTED AS A CAOF THE POSITION OF THE		UL REESTABLISHMENT	5.6 Ta	NO. 33985	
Signed by	What	NOT	TO THE	DATED NOV. 3, 2000	
Signed by EDWARD W. RE	ED .	- LINE COST DIO	TMENTAL MA	,P-	
Surveyor's Michigan License	•	- Caranteposts	5 Olive	63.85 ES	
, , , , , , , , , , , , , , , , , , ,		CPPY NOT TO B	O KERGASPROVED	CH: CH:	OFESSIONAL SURVEYORS. REVISED MAY 14.1975
JAN. 28, 1971	•	PERS FOR CO	PIES.		REVISED JAN., 1983 REVISED OCT., 1995