For corners in

SECTION

BRANCH COUNTY REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE OF MICHIGAN
Filing Requirement of Act 74, Mich. P.A. 1970 Branch County Recorded

BRANCH (County)	Located In:	Corner Code ##	10.70 1000 11.01.00
GIRARD TWP.			12-30-1999 11:01:08
Public Land Survey	T_5_S_R_6_W	M-5	Linda Lee Morrison-Mathews
	T R T R		REGISTER OF DEEDS
•	. T R		Liber 00004 Page 0052
2. Property Controlling	S T R		Liber UUUU Page UUJL
in Section	S T R	· .	
Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
•		. •	,
	ecorded Plat		A B C D E F G H 1 J K L M
5. Private Claims		<u> </u>	2 6 5 4 3 2
,		·	3
			4 - 7 - 8 - 9 - 10 - 11 - 12 - 1
I, EDWARD W. REED .	in a field survey onOCT airements of P.A. 74, Michigan P.A. o	21 , 19 <u>99</u> of 1970, the corner points men	utioned T
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land			
	ctions of the United States Depart Court of Law and/or that the corner		"Land
above were in conformance with	the rules of the Michigan Board of -established, monumented, re-m	Land Surveyors or by a Decr	ree of a
expressed below:	-established, monumented, re-in	onumented, recovered, rou	10 30 29 28 27 26 25
	rners, all in the same town and	d range, may be recorded	
on this certificate.		•	12 31 32 33 34 35 36
A. Description of original m	onument and accessories and	or subsequent restoration	n:
SOUTHEAST CORNER TO	SECTION 12		ACCEPTED BY THE BRANCH COUNTY
NORTHEAST CORNER TO	SECTION 13	•	SURVEY PEER GROUP AS THE OFFICIAL Corner under michigan public act 345
1825: JOHN MULLETT,	CORNER SET		OF 1990 AT A MEETING HELD ON
1825: ROBERT CLARK,	JRGLO OFFSET OF 31		E.R. Reed P.S.
SURVEYOR'S OL	D NOTES INDICATE TILE	& STONE	E.R. REED
B. Description of corner evi	dence found and/or method as	oplied in restoring or rees	tablishing corner:
DUG @ GLO OFFSET &	FOUND 10" POINTED STO	NE (NO TILE)	
SET 1/2" x 18" REBAR	R IRON WITH REMON CAP	IN CAST IRON MONUM	IENT BOX 4" BELOW GRAVEL ROAD SHOULDER
		·	
		•	
•		-	
C. Description of monumen	t for corner and accessories es	stablished to perpetuate le	ocating the position of the corner:
1/2" x 18" REBAR IRO	N WITH REMON CAP IN C		
POST N77W		137.30' 213.66'	OF MICH
TELEPHONE POLE N83W TELEPHONE POLE N71W	•	186.3'	EDWARD
10" OAK S36W	•	22.91	W. REED
BUTLER CORNER A-5		NORTH 21.06'	LAND SURVEYOR
	CAREFUL AND FAITHFUL	PERPETUATION	NO. 8
OF THE POSITION OF	THE ORIGINAL CORNER.		33985
	\sim \sim		ULAND SU
=			- LANCONING -
Signed by	m VV/ m	Date	OCT 21, 1999
Surveyor's Michigan License	W. REED No33985		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971