SURVEY & REMONUMENTATION

MAR 1 3 1998

SECTION

BRANCH COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE OF MICHIGAN

Filing Requirement of Act 74, Mich. P.A. 1970 Branch County Recorded For corners in Corner Code # Located in: 10-22-1997 09:58:40 BRANCH (County) UNION TWP. Linda Lee Morrison-Mathews T<u>58</u>R<u>7W</u> A-5 REGISTER OF DEEDS 1 Public Land Survey Liber 00003 Page 0181 Т 2. Property Controlling T in Section R T Register of Deeds Stamp & File Number 3. Miscellaneous R Property in Sec. ___ , Recorded Plat 5. Private Claims , in a field survey on <u>April 20</u>, 19<u>97</u> EDWARD W. REED state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: SOUTHWEST CORNER SECTION 7, NORTHWEST CORNER SECTION 18 1826: R. CLARK, jr. - CORNER SET OLD SURVEY NOTES INDICATE STONE AND/OR IRON 1973; E.R. REED - DUG FOR CORNER, FOUND OLD GATE LATCH (IRON) EXACTLY ON FENCELINE RUNNING EAST, ALSO FOUND PIECE OF TILE, FITS FENCELINE OF OLD SCHOOL SITE, SET RLS CAPPED IRON IN PLACE OF OLD GATE LATCH, RECORDED IN LCRC # 0073 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND ERR CAPPED IRON STAKE Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET REMON CAP ON 1/2" EXISTING IRON, SET CI-MONUMENT BOX FLUSH WITH ROAD SURFACE CENTER OF 48" MAPLE, EAST 19.0' CENTERLINE OF NORTH-SOUTH ROAD, WEST 10.4' IN LINE WITH FENCELINE RUNNING EAST NAIL/SHINER SOUTH SIDE POWER POLE, N17W 105.12' NAIL/SHINER EAST SIDE POWER POLE, S25W 110.41' 122 LINKS SOUTH OF M-5 SHERWOOD AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER Date <u>April 20, 1997</u> Signed by _ OF SICE OF SIC EDWARD W. REED

> Red P.S. Co. Rep. E.R. REFD

ACCEPTED BY THE BRANCH COUN SURVEY PEER GROUP AS THE OFFICE CORNER UNDER MICHIGAN PUBLIC ACT 8 OF 1991, AT A MEETING HELD

33985

W. REED

LAND

Surveyor

NO.

33985 CED LAND S LAND STATE

Surveyor's Michigan License No.

REVISED MAY 14,1975 REVISED JAN., 198

OVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28

REVISED OCT., 199