FEB 0 0 1999 Í

METOTICAL

Surveyor's Michigan License No. 33985

BRANCH COUNTY REMONUMATION PROGRAM DELICIO Page 0252 LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SRANDE COUNTY Located in: Corner Code #			· .	
1. Public Land Survey T. R. T. R.	BRANCH COUNTY	Located In:	Corner Code #	Branch County
Linda Lee Montison-Mathreus T R R R R REGISTER OF DEEDS REGISTER OF		E = 0	0.05	12-07-1998 13:54:00
2. Property Controlling S T R R 3. Miscellaneous S T R Property in Sec. S T R Property in Sec. S T R 4. Lot No, Recorded Plat	1. Public Land Survey	TR	G-05	Linda Lee Morrison-Mathews
in Section S. Miscellaneous T. R. Property in Sec. S. Property in Sec. Sec. Sec. Sec. Sec. Sec. Sec. Sec.	2 Property Controlling			Davidson of Davids Chambar 9 File Nismbor
3. Miscellaneous Property in Sec. T. R. 4. Lot No, Recorded Plat 5. Private Claims 1	• •	S		Register of Deeds Statish & File Reliabel
Property in Sec. T. R. E.R.REED 4. Lot No, Recorded Plat	3. Miscellaneous			CORRER UNDER MICHIGAN PUBLIC ACT 345
4. Lot No, Recorded Plat	Property in Sec.	S		E.R. Reed, Co. Rep.
5. Private Claims I. EDWARD W. REED., in a field survey on OCTOBER 30., 19 98. do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bursau of Land Management or by a decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. CORNER COMMON TO SECTIONS 9-10-16-16 A. Description of original monument and accessories and/or subsequent restoration: 1825: R. CLARK, JR., DEPT SURVEYOR - CORNER SET 1856: A.R. DAY, CO SURVEYOR - STONE OVER STAKE 1991: F.J. CUTCHER, SURVEYOR - STONE OVER STAKE 1991: F.J. CUTCHER, SURVEYOR - STONE OVER STAKE 1991: F.J. CUTCHER, SURVEYOR - RION OVER STONE SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN C-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN C-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN C-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN C-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN C-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN C-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN C-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET X TRANCHOR POST NORTH 27.67' WITHINESS TAG IN W. SIDE 10" OAK \$4.7E 90.74' BASE OF SQUARE CONC. POST N 38 W 39.7' IN LINE WITH FENCE LINE RUNNING NORTH AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER		V		E.R.REED
5. Private Claims 1. EDWARD W. REED., in a field survey on OCTOBER 30., 19_98. do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors of ya Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. CORNER COMMON TO SECTIONS 9-10-15-16 A. Description of original monument and accessories and/or subsequent restoration: 1825: R. CLARK, JR., DEPT SURVEYOR - CORNER SET 1825: R. CLARK, JR., DEPT SURVEYOR - CORNER STAKE 1991: F.J. CUTCHER, SURVEYOR - IRON OVER STONE B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND F.J. CUTCHER'S CAPPED IRON OVER STONE 20" DEEP C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET 1/2" X 18" REBAR IRON OVER CUTCHER'S IRON IN CI-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET REMON, CAP ON REBAR. 2" ROUND STEEL ANCHOR POST NORTH 27.67" WITHESS TAG IN W. SIGD 10" OAK S 47 E 90.74' BASE OF SOUARE CONC. POST N 38 W 39.7' IN LINE WITH FENCE LINE RUNNING NORTH AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER	4. Lot No, Rec	corded Plat		
I, EDWARD W. REED., in a field survey on OCTOBER 30. 19 98. do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3.4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyers or by a Docree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more then 2 comers, all in the same town and range, may be recorded on this certificate. CORNER COMMON TO SECTIONS 9-10-15-15 A. Description of original monument and accessories and/or subsequent restoration: 1825: R. CLARK, JR., DEPT SURVEYOR - CORNER SET 1856: A.R. DAY, CO SURVEYOR - STONE OVER STAKE 1991:, F.J. CUTCHER, SURVEYOR - IRON OVER STONE 20" DEEP C. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND F.J. CUTCHER'S CAPPED IRON OVER STONE 20" DEEP C. Description of monument for comer and accessories established to perpetuate locating the position of the corner: SET Y." X 18" REBAR IRON OVER CUTCHER'S IRON IN CI-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET REMON. CAP ON REBAR. 2" ROUND STEEL ANCHOR POST NORTH 27.67' WITNESS TAG IN W. SIDE 10" OAK S 47 E 90.74' BASE OF SQUARE CONC. POST N 38 W 39.7' IN LINE WITH FENCE LINE RUNNING NORTH AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER	5. Private Claims			_ 1
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. CORNER COMMON TO SECTIONS 9-10-15-16 A. Description of original monument and accessories and/or subsequent restoration: 1825: R. CLARK, JR., DEPT SURVEYOR - CORNER SET 1866: A.R. DAY, CO SURVEYOR - STONE OVER STAKE 1991:. F.J. CUTCHER, SURVEYOR - IRON OVER STONE B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND F.J. CUTCHER'S CAPPED IRON OVER STONE 20" DEEP C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN CI-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET REMON. CAP ON REBAR. 2" ROUND STEEL ANCHOR POST NORTH 27.67' WITNESS TAG IN W. SIDE 10" OAK S 47 E 90.74' BASE OF SQUARE CONC. POST N 38 W 39.7' IN LINE WITH FENCE LINE RUNNING NORTH AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER LAND SURVEYOR NO. 39985 LAND SURVEYOR NO. 39985 LAND SURVEYOR NO. 39985 LAND SURVEYOR NO. 39985	that under requirements of P lines 1 and 2 above were in co- current manual of survey instru- Land Management or by a dec- lines 3, 4 and 5 above were Surveyors or by a Decree of	.A. 74, Michigan P.A. of 1970 onformance with regulations and uctions of the United States Departed of a Court of Law and for the in conformance with the rules of a Court of Law; established	, the corner points mentioned in I rules therefore as required in the partment of the Interior, Bureau of pat the corner points mentioned in sof the Michigan Board of Land	3 4 -7 - 8 - 9 - 10 - 11 - 12 5 6 - 18 - 17 - 16 - 15 - 14 - 13 7
A. Description of original monument and accessories and/or subsequent restoration: 1825: R. CLARK, JR., DEPT SURVEYOR - CORNER SET 1856: A.R. DAY, CO SURVEYOR - STONE OVER STAKE 1991:. F.J. CUTCHER, SURVEYOR - IRON OVER STONE B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND F.J. CUTCHER'S CAPPED IRON OVER STONE 20" DEEP C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN CHMONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET REMON. CAP ON REBAR. 2" ROUND STEEL ANCHOR POST NORTH 27.67' WITNESS TAG IN W. SIDE 10" OAK S 47 E 90.74' BASE OF SOUARE CONC. POST N 38 W 39.7' IN LINE WITH FENCE LINE RUNNING NORTH AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER				10 30 29 28 27 26 25
A. Description of original monument and accessories and/or subsequent restoration: 1825: R. CLARK, JR., DEPT SURVEYOR - CORNER SET 1856: A.R. DAY, CO SURVEYOR - STONE OVER STAKE 1991:. F.J. CUTCHER, SURVEYOR - IRON OVER STONE B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND F.J. CUTCHER'S CAPPED IRON OVER STONE 20" DEEP C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN CI-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET REMON. CAP ON REBAR. 2" ROUND STEEL ANCHOR POST NORTH 27.67' WITNESS TAG IN W. SIDE 10" OAK S 47 E 90.74' BASE OF SQUARE CONC. POST N 38 W 39.7' IN LINE WITH FENCE LINE RUNNING NORTH AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER	CORNER COMMON TO SECTION	NS 9-10-15-16		
1856: A.R. DAY, CO SURVEYOR - STONE OVER STAKE 1991:. F.J. CUTCHER, SURVEYOR - IRON OVER STONE B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND F.J. CUTCHER'S CAPPED IRON OVER STONE 20" DEEP C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN CI-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET REMON. CAP ON REBAR. 2" ROUND STEEL ANCHOR POST NORTH 27.67' WITNESS TAG IN W. SIDE 10" OAK S 47 E 90.74' BASE OF SQUARE CONC. POST N 38 W 39.7' IN LINE WITH FENCE LINE RUNNING NORTH AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER	, -	al monument and accessori	es and/or subsequent	13
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN CI-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET REMON. CAP ON REBAR. 2" ROUND STEEL ANCHOR POST NORTH 27.67' WITNESS TAG IN W. SIDE 10" OAK S 47 E 90.74' BASE OF SQUARE CONC. POST N 38 W 39.7' IN LINE WITH FENCE LINE RUNNING NORTH AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER	1856: A.R. DAY, CO SUR	VEYOR - STONE OVER STA	KE	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN CI-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET REMON. CAP ON REBAR. 2" ROUND STEEL ANCHOR POST NORTH 27.67' WITNESS TAG IN W. SIDE 10" OAK S 47 E 90.74' BASE OF SQUARE CONC. POST N 38 W 39.7' IN LINE WITH FENCE LINE RUNNING NORTH AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER	B. Description of corner e	vidence found and/or method	I applied in restoring or reestal	blishing corner:
SET ½" X 18" REBAR IRON OVER CUTCHER'S IRON IN CI-MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE SET REMON. CAP ON REBAR. 2" ROUND STEEL ANCHOR POST NORTH 27.67' WITNESS TAG IN W. SIDE 10" OAK S 47 E 90.74' BASE OF SQUARE CONC. POST N 38 W 39.7' IN LINE WITH FENCE LINE RUNNING NORTH AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER	FOUND F.J. CUTCHER'S C	CAPPED IRON OVER STONE	20" DEEP	
SET REMON. CAP ON REBAR. 2" ROUND STEEL ANCHOR POST NORTH 27.67' WITNESS TAG IN W. SIDE 10" OAK S 47 E 90.74' BASE OF SQUARE CONC. POST N 38 W 39.7' IN LINE WITH FENCE LINE RUNNING NORTH AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER OF THE POSITION OF THE ORIGINAL CORNER	C. Description of monume	ent for corner and accessories es	stablished to perpetuate locating	the position of the corner:
AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER W. HEED LAND SURVEYOR NO. 33985 LAND LAND SURVEYOR	SET REMON. 2" ROUND STEEL ANCHO WITNESS TAG IN W. SIDE BASE OF SQUARE CONC.	CAP ON REBAR. R POST NORTH 27.67 10" OAK S 47 E 90.74 POST N 38 W 39.7'	1	OF MICHIGA
Signed by Signed by Date NOVEMBER 4, 1998	AND IS ACCEPTED AS A OF THE POSITION OF THE	CAREFUL AND FAITHFUL PI E ORIGINAL CORNER	ERPETUATION	LAND SURVEYOR
Signed by Date NOVEMBER 4, 1998				ব্যক্ত দুসাম প্
EDWADD W DEED	Signed by	w. N. ry		Date NOVEMBER 4, 1998