SURVEY & REMONUMENTATION

ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON

APR 2 6 1995

EReed C. Rop.

BRANCH COUNTY NATION CORNER LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

_			
FOR	COTH	arc	15

, ,				
	Branch	Located In:	Corner Code =/-#	
1.	(County) Public Land Survey	T _5_SR _7_W T R T R	K_2	STATE OF MICHIGAN Branch County Recorded
		T R		12-28-1994 15:01:36
2.	Property Controlling in Section	S T R S T R		Linda Lee Morrison-Mathews
3.		S T R		Register of Deeds Stamp & File Number
٠.	Property in Sec.	S R		· · ·
	, ,			Liber 00002 Fage 0296
		Recorded Plat		A B C D E F G H I J K L M
5.	Private Claims			
		•		
,	Edward W Poo	d in a field survey onDece	ember 8 1994	5
do	hereby certify that under re	equirements of P.A. 74, Michigan P.A.	of 1970, the corner points menti	oned all llll
in	lines 1 and 2 above were i	in conformance with regulations an	id rules therelore as required in	n the
cu	rrent manual of survey instr	ructions of the United States Depar a Court of Law and/or that the corne	tment of the interior, Bureau of	Land
Ma ah	inagement of by a decree of overwere in conformance w	ith the rules of the Michigan Board o	of Land Surveyors or by a Decre	enta IIIIIIIIIII
Co	urt of Law; established;	re-established, monumented, re-r	nonumented, recovered, foun	d as
	pressed below:	•		10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			11	
	on this certificate	•		12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

Quarter corner common to Sections 1 and 2, Town 5 South, Range 7 West, Union Twp. Branch County, Michigan.

1885: GLO notes set quarter corner 1873: Ricker, stone and cobbles set

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Proportioned actual and GLO distances north and south Dug for corners and found nothing


Set %"x18" rebar iron in monument box with remonumentation cap on line of north and south Section corners and midway in distance.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/2" Iron as noted above:

½" Iron as noted above:

NE corner house, (not porch), \$30W 232.30



Nail & washer 2 up N. side power Nail & washer 2' up Power Pole, N in C/L N-S road			W. REED LAND SURVEYOR NO. 33985 SED LAND SURVEYOR
And is accepted as a careful a	ind faithful	reestablishment of	the
postion of the original corner. Signed by	Date	_December_8,_1994	
Surveyor's Michigan License No. 33985 W. 72EED.		FORM APPROVED BY MICHIGAN STATE BOARD	OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983