SURVEY & REMONUMENTATION

MAR 1 3 1998

SECTION

Ear corners in

BRANCH COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE STATE OF MICHIGAN Filing Requirement of Act 74, Mich. P.A. 1970 Branch County Recorded

	BRANCH COUNTY											
	SHERWOOD TW	IP. Located In:	Corner Code ##	10-22-1997 09:58:10								
1.	Public Land Survey	T <u>5 S</u> R <u>8 W</u> T R	<u> </u>	Linda Lee Morrison-Mathews REGISTER OF DEEDS								
2	Property Controlling	T R T R S T R		Liber	000	03	Pa:	₃e [jį	7 7	7	
۲.	in Section	S R										
3.	Miscellaneous	S R		Register of	Doode	Ctan	. n. P.	Eilo	Misse	aha.	_	
	Property in Sec.	S T R		negister of	Deeds	Jiani	ıp ox		IVUII	ibei		
		S	SHERWOOD TWP.									
				A !	3 C D	E F	; G	н	ı j	ĸ	Ł	м
5.	Private Claims			— <u>,</u> []		\top		1		\Box	Ţ	
				3	7-1-1-	┪┪		-3-	一		-ì	
				1		11	\top	\top	\Box	十	\exists	_
	ENWARD P. REED	V to a Catal accessor	JULY 31 , 19 97	<u>*</u> ⊢7	-18-	9	1	-10	1	' 🕇	— 12 	:
do.	hereby certify that under rec	nd l			_	_	1	一	-			
in i	lines 1 and 2 above were in	ie • -18		16	}	-15 I	†*	╌┼	— i3	; —		
	current manual of survey instructions of the United States Department of the Interior, Bureau of Land					+	\dashv	+-	+	\dashv	-	-
	Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a					- 2 1	-	-22	2	} 	<u>24</u>	, —
	Court of Law, established, re-established, monumented, re-monumented, recovered, found as					+			╂━┫		-	
ext	expressed below:					28		-27	1-2	;	25	<u>; </u>
NC	NOTE: Not more than 4 corners, all in the same town and range, may be recorded								╁╾┤	\dashv	+	_
	on this certificate.			1231	32	33	, 	-34	-3!	;—	— 36	<u>, </u>
				13		\bot		Щ	\sqcup			
A.	Description of original monument and accessories and/or subsequent restoration:											
	JOHN MULLETT, D.S. 1826: "NORTH BETWEEN SEC'S. 29 & 30, 80.00 SET POST COR. SEC'S 19, 20, 29 & 30. W OAK 14 N12W 39, W OAK 14 S39 1/2W 33."											
			NIZW 39, W OAK 14 83921 : MADE A SURVEY OF S. (CTION	20						
		•	S CORNER ON HIS SURVEY		CITON	20,	80	/ I G	/ A V E			
	,		TONE SET MANY YEARS AG		. 11							
			STONE (POINTED) 12" (RY	BBI	CK				
		TILE OR CHINA. SET 1			V110C0	0.	J.()	J.(
		L.C.R.C. 1/97 - "IRO										

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

E. R. REED, 1974: BLOSSOM LAKE PLAT REFERENCED TO THIS CORNER.

FOUND A $\frac{1}{2}$ " REBAR STAKE, FROM WITNESSES GIVEN ON MY 1969 FIELDNOTES AND L.C.R.C. 1/97 BY R. CARR, 1974.

PLACED A BRANCH COUNTY REMONUMENTATION CAP ON REBAR STAKE, SET ALL IN CONCRETE, AND PLACED C-I MONUMENT BOX OVER IT;

AND ACCEPTED IT AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A BRANCH COUNTY REMONUMENTATION CAP ON $\frac{1}{2}$ " REBAR STAKE, SET IN CONCRETE, IN C-1 MONUMENT BOX:

EDWARD R

REED, PROFESSIONAL SURVEYOR

N 50 W 76.2' - N E CORNER OF HOUSE.

S 50 W 78.8' - S E CORNER OF GARAGE.

S 88 W 28.7' - CENTER OF 16" MAPLE.

S 45 E 118.6' - N W CORNER OF HOUSE.

N 80 W 65.3' - S E CORNER OF HOUSE.

N 45 E 51.5' - FACE OF P. POLE.

\$ 40 E 65.5' - CENTER OF 42" MAPLE.

ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON

E.R. REED, P.S.

JULY 31, 1997

Signed by EDWARD R. REED, P.S. Surveyor's Michigan License No.

7437