## SURVEY & REMONUMENTATION

MAR 2 1 1997

COMMISSION

## BRANCH COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			, Liber 00003 Page 0091
BRANCH	. Located In:	Corner Code ##	STATE OF MICHIGAN
SHERWOOD TWP.			Branch County
Public Land Survey	т <u>5 s я 8 w</u>	<u>H-11</u>	Recorded
	T Ř		
	T R	·	10-30-1996 09:22:53
	T R		Linda Lau Mandalana Meddaesa
	S R		Linda Lee Morrison-Mathews REGISTER OF DEEDS
	S T R S T R		
	S R		Register of Deeds Stamp & File Number
riopenty in oco.	<u> </u>	······································	<u> </u>
4. Lot No, Rec	orded Plat		A B C D E F G H I J K L M
5. Private Claims			
·			2 - 6 - 5 3 2 1 - 1
			3
	- COTTOD		4 - 7 - 8 - 1 - 9 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
1, EDWARD W. REED , in a field survey on OCTOBER 8 , 19 96 , 5 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned			
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the			
current manual of survey instructions of the United States Department of the Interior, Bureau of Land			
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a			
Court of Law; established, re-e	stablished, monumented, re-mo	onumented, recovered, fou	ind as
expressed below:		•	10 30 29 28 27 26 25
NOTE: Not more than 4 corn	ers, all in the same town and	i range, may be recorded	1 1 1 1 1 1 1 1 1 1 1 1 1
on this certificate.	·		12 31 32 33 34 35 36 13 13 13 13 13 13 13 13 13 13 13 13 13
A. Donneistian of original ma	nument and accessories and/	or subsequent restoration	
A. Description of original monument and accessories and/or subsequent restoration:			
QUARTER CORNER COMMON TO SECTIONS 34 & 27, T5S, R8W, SHERWOOD TWP., BRANCH COUNTY, MI 1825: J. MULLETT, D.S., CORNER SET			
1825: J. MULLETT, D.	S., CORNER SET	ER @ AVERAGE DISTA	NOTE AND IN RIGHT LINE AND PLANTED STONE
1879: BENNETT, NO CORNER FOUND, SET CORNER @ AVERAGE DISTANCE AND IN RIGHT LINE AND PLANTED STONE 1882: HAMILJON, COUNTY SURVEYOR, FOUND STONE			
1895: I.D. MINER, COUNTY SURVEYOR, FOUND STONE			
1974: DAVID BOONE SURVEYOR, FOUND STONE IN ROAD DOWN 2.5', SET CASTING AND IRON PIN OVER STONE			
RECORDED L.C.R			
B. Description of corner evid	ence found and/or method ap	plied in restoring or rees	stablishing corner:
FOUND SMALL IRON IN C	AST IRON BOX		
		ITH REMONUMENTATIO	ON CAP IN CAST IRON BOX
RAISED BOX TO ROAD SU	RFACE WITH RINGS		
			OF M/C
•	•		
			EDWARD
			W. REED
•			LAND SURVEYOR
			NO.
		•	33985
•	·		DED LAND SURPLE
			Manufacture of the second of t
C Description of monument	for corner and accessories es	stablished to perpetuate	ocating the position of the corner:
1/2" x 18" REBAR WITH			·
S50W 39.72' TO FACE O			ACCEPTED BY THE BRANCH COUNTY Survey Peer Group as the Official
S35W 73.49' TO FACE C			CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON
S56E 68.76' TO CENTER			oct. 9, 1996
N65E 125.5' TO SW COR			EA. Red Co. Rev.
N44E 49.1' TO FACE OF			E R REED
S45W 41.2' TO FACE OF	' RAILROAD RAIL FENCE	CORNER POST	L.N. NELD
AND IS ACCEPTED AS A	CAREFUL AND FAITHFUL	PERPETUATION OF T	THE POSITION OF THE ORIGINAL CORNER.
	_ 1	•	
C./			
Signed by	W. Kul	Date	OCTOBER-8, 1996
EDWARD	W. REED	985	COLD ASSESSED BY MICHIGAN STATE BOARS OF LAND CHRYCYCES JAM 22 1971
Surveyor's Michigan License N	1033	/3/.J.	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983