State & Commission RELIANCE LANGE

FEB 032000

BRANCH COUNTY REMONUMATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 President County

Branch.	County
Recorde	ed

SEC			O	1	V
	į,	ě	40	5	A

EDWARD W. REED

33985

Surveyor's Michigan License No.___

- or corners in			11-08-1999 15:11:55
BRANCH COUNTY BUTLER TWP	Located In:	Corner Code #	Linda Lee Morrison-Mathews REGISTER OF DEEDS
1. Public Land Survey	T <u>5S</u> R <u>5W</u> TR TR TR	<u>I-11</u>	Liber 000 04 Page 001 4
Property Controlling in Section	S TR S T R		Register of Deeds Stamp & File Number ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL
3. Miscellaneous Property in Sec.	S TR S T R		OF 1990 AT A MEETING HELD ON OCC. C. Rep.
4. Lot No, Re	ecorded Plat		E.R. REED
5. Private Claims		ii ii	A B C D E F G H I J K L 1
state that under requirements in lines 1 and 2 above were i the current manual of surve Bureau of Land Management mentioned in lines 3, 4 and 5	in a field survey on <u>SEPTEMBI</u> of P.A. 74, Michigan P.A. of 18 n conformance with regulations ay instructions of the United State or by a decree of a Court of La above were in conformance with cree of a Court of Law; established below:	770, the corner points mentioned and rules therefore as required in ites Department of the Interior, w and /or that the corner points in the rules of the Michigan Board	3
NOTE: Not more than 2 comon this certificate.	ners, all in the same town and ran	ge, may be recorded	9 10 30 29 28 27 26 25
CORNER COMMON TO	SECTIONS 26-27-34-35, BU	JTLER TWP.	12 31 32 33 34 35 36
A. Description of originarestoration:	al monument and accessorio	es and/or subsequent	13
1825: R. CLARK, JR C 1878: M. KNOWLES - SI	CORNER SET ET STONE 14 AND STONES	3	
B. Description of corner e	evidence found and/or method	applied in restoring or reestabli	ishing corner:
FOUND ½" X 18" PIPE I	N LINE WITH FENCES N &	S. FOUND SMALL STONES	AROUND PIPE.
C. Description of monum	ent for corner and accessor	ries established to perpetuate	e locating the position of the corner:
SET ½" X 18" REBAR IRC	ON WITH REMON CAP IN CI-N	MONUMENT BOX 4" BELOW	GRAVEL ROAD SURFACE.
DUE NORTH 30.38' R N 75 E 73.2' C	OUND WOOD ANCHOR POS	т	EDWARD W. REED LAND SURVEYOR NO.
AND IS ACCEPTED AS TH OF THE POSITION OF THE	•	2	CAND SURVEY OF LAND SURVEY
Signed by	Edm W. K	uf	Date <u>SEPTEMBER 28,1999</u>