SURVEY & REMONUMENTATION

FEB 1 3 2001

BRANCH COUNTY REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE STATE OF MICHIGAN Filing Requirement of Act 74, Mich. P.A. 1970 Branch County Recorded

For corners in	:		1	12-15-2000 14	rogrād ·
BRANCH COUNTY QUINCY TWP	Located In:	Corner Code #		inda Lee Mor. ŒGISTER OF D	rison-Mathews EEDS
1. Public Land Survey	T <u>6\$</u> R <u>5W</u> TR TR	<u>G-12</u>	Li		i Page CISS
in Section S	T R			Register of Deed	s Stamp & File Number
3. Miscellaneous ST	R		CORNI	PTED BY THE EY PEER GROUP ER UNDER MICHIGA 1990 AT A MES 28.2000	BRANCH COUNTY AS THE OFFICIAL N FUBLIC ACT 345 TING HELD ON
Property in Sec. ST	R		and a Committee	E.R.	Red, P.S.
4. Lot No, Recorded	i Plat	•		BCDE	F G H I J K L M
5. Private Claims			1 2		4 -3 -2 -1-
I, EDWARD W. REED, in a fix requirements of P.A. 74, Michigan P above were in conformance with remanual of survey instructions of the Management or by a decree of a Cou 3, 4 and 5 above were in conformance by a Decree of a Court of Law; et as expressed below:	.A. of 1970, the corner populations and rules ther United States Department of Law and for that the ce with the rules of the N	points mentioned in lines efore as required in the nt of the Interior, Bureau a corner points mentione lichigan Board of Land S	s 1 and 2 e current u of Land d in lines durveyors ed, found 8	10 17 1	9 10 11 12 6 15 14 13 24
NOTE: Not more than 2 comers, all on this certificate.	in the same town and ran	ge, may be recorded	9 - 10 - 11 -	_30292	8272625
QUARTER CORNER COMMON T COUNTY, MI	O SECTIONS 33 & 34	QUINCY TWP., BRA	NCH 12	_31323	3-343536
A. Description of original monun restoration: 1825: ORANGE RISDON-CORNE 1998: JOHN E. MAXSON, P.SS 1999: JOHN E. MAXSON, P.SS THE 1/4 CORNER BUT TH NO. LCRC'S HAVE BEEN	R SET SURVEY TIED TO COR SURVEY-BOTH 1998 & IERE ARE NO WITNES	NER-NO WITNESS O 1999 SURVEYS BY SES TO OR INDICAT	MAXSON MA ION OF THE N	KË REFERENCE	AS BEGINNING AT
B. Description of corner evidence NO EVIDENCE OF CORNER-ORIG DEPARTMENT SET POINT ON LINE & MIDWAY SET ½" X 18" REBAR IRON WIT SURFACE	BETWEEN RECORDE	GONE DUE TO MAJO CORNERS NORTH	OR ROAD REBU & SOUTH	JILDING BY CO	
C. Description of monument for 6 1/2" X 18" REBAR IRON WITH RE TAG EAST SIDE OF POWER POL SOUTH END OF ROAD CULVERT TELEPHONE PEDESTAL CENTERLINE NORTH-SOUTH RO	MON CAP IN CAST IF E -	RON REMONUMENTA N44W S72E	etuate locating ATION BOX FLU 73.0' 41.3' 58.5'	the position of JSH WITH PAV OF MICH EDWARD W. REED	the corner: YED ROAD SURFACE
AND IS ACCEPTED AS A CAREF OF THE POSITION OF THE ORIGI		ESTABLISHMENT		LAND SURVEYOR NO.	
Signed by Salme 10	Luy		100	33985 SOLANDS	Σ T. 10, 2000
EDWARD W. REED) 5. 33985	A Company of the Company	rii Drii John	- * 4 4 4 4 4 4 4	
Surveyor's Michigan License No	, C	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	OEGIO,	TE BOARD OF PROFESS	ional Surveyors, Jan. 28, 1971 Revised May 14,1975 Revised Jan., 1983 Revised Oct., 1995
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Section 1	COPY PUBLIC TO SEMD PUBLIC TO PEED'S FOR CO	r-11		