ECD (2000

BRANCH COUNTY REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE OF MICHIGAN Filing Requirement of Act 74, Mich. P.A. 1970 Stranch County

Recorded

				' -
100		Primer	B ***	14 A
1	200 E	- 1.	ra an	1.5
. "	P 1	ar I'	1.12. 1.	. 75

For corners in			•		12-30-199	9 11:02:26	;	
BRANCH COUNTY QUINCY TWP	Located In:		Corner Code	#	Linda Lee REGISTER (-Mathe	JS
1. Public Land Survey	T <u>6S</u> R <u>5</u> TR_		<u>J-1</u>		Liber OC)004 pa	aae O (360
Property Controlling in Section	T R S T R S T R		·		Register	of Deeds Sta	mp & Fi	le Numbe
3. Miscellaneous	S T R				ACCEPTED SURVEY PI CORNER UN OF 1990	BY THE E ER GROUP A IDER MICHIGAL AT A MEE	BRANCH AS THE N PUBLIC TING H	OFFICIAL ACT 345 ELD ON
Property in Sec.	S T R				DEC. O	7, 1999 F.R.Rec E.R.REE	d , P. D	<u>s. </u>
4. Lot No, Re	corded Plat			.,	а в с	DEFG	- 1 - 1	.1 K 1.
5. Private Claims					1	5 4	3-1	-2 -1
I, EDWARD W. REED, under requirements of P.A. 7 and 2 above were in conformational of survey instructions Management or by a decree of 3, 4 and 5 above were in conformation or by a Decree of a Court of as expressed below:	 Michigan P.A. of 197 Michigan P.A. of 197	O, the cor d rules the epartment that the of the Mic	rner points mention refore as required in c of the Interior, Bur corner points menti chigan Board of Lar	ed in lines 1 in the current reau of Land oned in lines ad Surveyors	3 4 — 7 5 6 — 18 7 8 — 19	89	-10	-1112 -1413 -2324
NOTE: Not more than 2 comon this certificate.	ners, all in the same town	and rang	e, may be recorded		9 30 30 11	29 20	_27	-26 -25
NORTH QUARTER CORNE	R SECTION 2, QUINC	CY TWP.			12 31	3233	34	_3536
A. Description of original restoration:	monument and acces	sories ar	nd/or subsequent		13			
1825: JOHN MULLET-CO 1878: M. KNOWLES-SUR OLD SURVEY NO							. ,	
B. Description of corner e	vidence found and/or	method	applied in restor	ing or reestab	lishing corne	er:	,	
TAKING FENCE AND OCC SET ½" X 18" REBAR WI	CUPATIONS LINES EA TH REMON CAP IN C	ST AND AST IRO	WEST, DUG HO N MONUMENT E	LE & FOUND BOX FLUSH W	POINTED ST /ITH PAVED	ONE ROAD SUR	RFACE	
C. Description of monume	ent for corner and acc	essories	established to pe	erpetuate loca	iting the pos	ition of the	corner	
½" X 18" REBAR WITH R NE CORNER FAP MARKEI NE CORNER TELEPHONE ROUND WOOD ANCHOR CENTER 42" MAPLE CENTER OF 6" PINE	R PEDESTAL	S39W 4 S62W 0 S30E 5 N4W 4 N68W	48.00' 61.60' 1.6' 2.2'	FLUSH WITH	ill E	D SURFAC DWARD V. REED LAND RVEYOR	E	
AND IS ACCEPTED AS A OF THE POSITION OF THE			RPETUATION	٠	12.2	NO. 33985 LAND SURVE	8	
Signed by	w When					Date(OCT 20	, 1999
EDWARD W		_	··					
Surveyor's Michigan Lice	ense No. <u>3398</u>	5		=				