## SURVEY & REMONUMENTATION

APR 2 6 1995

## COMMISSION

## BRANCH COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE

| _   | Filing Requirer   | ment of Act 74, Mich. P.A   |   |
|---|---|---|---|
| For corners in  |   |   | STATE OF MICHAGAN   |
| Branch (County)   | Located In:   | Corner Code =##   | Branch Crunty<br>Recorded   |
| 1. Public Land Survey   | T <u>6 S</u> R <u>6 W</u><br>T R  | <u> </u>  | 12-28-1994 15:06:14   |
|   | T R<br>T R  |   | Linda In Common Mater 26  |
| <ul><li>2. Property Controlling in Section</li><li>3. Miscellaneous</li></ul>   | S T R<br>S T R<br>S T R   |   | Register of Deeds Stamp & File Number   |
| Property in Sec.  | S R   |   | register of beeds Staffip & File Number   |
| 4. Lot No, F 5. Private Claims  | Recorded Plat   |   | A B C D E F G H I J K L N   |
| ·   |   |   | 3   |
|   | , in a field survey onAugu  |   |   |
| in lines 1 and 2 above were in<br>current manual of survey instri<br>Management or by a decree of<br>above were in conformance wi | quirements of P.A. 74, Michigan P.A. of a conformance with regulations and uctions of the United States Departma Court of Law and/or that the corner part the rules of the Michigan Board of the established, monumented, re-mo | rules therefore as required in t<br>ent of the Interior, Bureau of La<br>points mentioned in lines 3, 4 an<br>_and Surveyors or by a Decree o | the and 7 d 5 8 19 20 21 22 23 24 50 a  |
|   | orners, all in the same town and  | range, may be recorded  | 11<br>12<br>31<br>32<br>33<br>33<br>34<br>35<br>36  |
| 1975: Boone, found 1  B. Description of corner e  Found 3/4" solid ire  | e set before  id stone  bund iron rod over stone  /2" iron pin in casting  vidence found and/or method ap   | g, recorded #142 plied in restoring or reestab  | olishing corner   |
| set 1/2 repar and 1   | emonumentation cap in c   | .asc from box   |   |
| ,   |   |   | EDWARD<br>W. REED   |
|   |   | •   | W. REED LAND SURVEYOR   |
|   |   |   | NO. 33985   |
| ž <sub>t</sub>  |   |   | CED LAND SUR  |
| 1/2" rebar as noted<br>South 45 East 74.95'<br>North 81 East 132.16<br>South 53 West 51.47'<br>North 16 East 134.75               | -to 14" maple '-to face of telephone -to face of telephone p '-to face of telephone -to face of telephone p   | pedestal<br>edestal<br>pedestal   | ating the position of the comer:  |
| South 23 East 133.55<br>South 77 West 109.1'<br>South 63 East 4.6'-i  | '-to northwest corner o<br>-to face of telephone p<br>ron in cast iron box as   | edestal<br>recorded by Boone  | foundation (not porch foundation)   |
| Signed by   | ufo Aug   | erpetuation of the p  | position of the original corner. August 26, 1994  |
| Edward W.<br>Surveyor's Michigan Licenso  |   | F.  | DAM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971<br>Revised May 14, 1975<br>Revised Jan., 1983 |