SURVEY & REMONUMENTATION

APR 2 6 1995

For corners in

expressed below:

COMMISSION

BRANCH COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

| Branch | Located In: | Corner Code =## | |
|---|--|--------------------------------|--|
| Public Land Survey | T <u>6 S R 6 W</u> T R T R | L-11 | STATE OF MICHIGAN Branch County Equapole 10002 Page 0328 12-28-1994 15:06:36 |
| Property Controlling in Section Miscellaneous Property in Sec. | T R S T R S T R S T R | | Linda Lee Morrison-Mathews REGISTER OF DEEDS Register of Deeds Stamp & File Number |
| | Recorded Plat | | A B C D E F G H I J K L N |
| do hereby certify that under re | , in a field survey onAugu equirements of P.A. 74, Michigan P.A. of | of 1970, the corner points men | tioned 6 |

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

A. Description of original monument and accessories and/or subsequent restoration: Quarter corner common to Sections 25 and 36, Town 6 South, Range 6 West, Coldwater Township, Branch County, Michigan.

1829: GLO notes, corner set

1904: Hamilton, found stone and cobbles, set plow point over same 1968: E. R. Reed, found stone and set $3/4^{\circ}$ iron and monument box over stone

1975: Boone, found 1/2" iron pin in casting, recorded #142

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1/2" iron pin set in cast from monument box Placed remonumentation cap on Iron



| C. Description of monument for corner and accessories established to perpetuate local | ating the position of the corner: |
|--|--|
| 1/2" rebar as noted above: South 25° East 35.91'-to walnut Center of concrete anchor post South 75 West 73.25'-nail and washer in 48" walnut North 41 East 35.45'-to face of telephone pedestal North 6 West 102.55'-to Southeast corner of housetrailer East to centerline drive South 98.0 | ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1980 AT A MEETING HELD ON 12-16-94. EROAD, Co. Rep. |
| | • |
| And is accepted as a careful and faithful perpetuation of the | position of the original corner. |

| Signed by Edward W. Reed | Date August 26, 1994 |
|---|--|
| Edward W. Reed Surveyor's Michigan License No33985 | FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 |
| | REVISED MAY 14, 1975 |
| | REVISED JAN., 1983 |