FEB 1 3 2001

4. Lot No.

5. Private Claims

## BRANCH COUNTY REMONUMENTATION PROGRAM

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION	Filing Requirement of Act 74, Mich. P.A.	. <b>1970</b> Branch County Recorded
BRANCH (County) BATAVIA TWP.	Located In: Corner Code ##	12-15-2000 14:09:17
Public Land Survey	T 6 S R 7 W J-07 T R T R	Linda Lee Morrison-Mathews REGISTER OF DEEDS
Property Controlling     in Section	S T R	Liber 00004 Page 0137
Miscellaneous     Property in Sec.	S T R	Register of Deeds Stamp & File Number

10

12 13 BATAVIA TWP., T6S, R7W

GHI

STATE OF MICHIGAN

I, EDWARD R. REED, P.,S in a field survey on OCTOBER 16, 2000 XX do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

\_\_\_ , Recorded Plat \_

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

QUARTER CORNER TO SECTIONS 14 & 23, T6S, R7W, BATAYIA TWP.:

1826 - G.L.O. FIELDNOTES OF WM. BROOKFIELD, D.S., "WEST BETWEEN SEC. 14 & 23- 39.91 SET QTR SEC. POST".

1880 - M. KNOWLES, CO. SURVEYOR, : "FD STONE WELL PLANTED & BRICK".

1969 - G. E. ANDERSON, MSHD: "FOUND REMNENTS OF A STAKE & 3/4" IRON PIPE 1'8" BELOW THE ROAD SURFACE. THE 3/4" PIPE WAS DRIVEN ALONGSIDE A 9"x7" STONE THE STONE WAS 3'8" BELOW ROAD SURFACE, WITH BROKEN BRICK AROUND STONE & PIPE. SET 1/2"x24" STEEL ROD IN MON. BOX.

1991 & 1992 - SURVEYS BY E.W. REED, L.S., REFERENCED TO SAID IRON ROD IN MON. BOX.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND THE STEEL STAKE IN THE MONUMENT BOX AS REFERENCED BY G.E. ANDERSON, MSHD.

I PLACED A BRANCH COUNTY REMONUMENTATION CAP ON SAID STEEL STAKE,

AND ACCEPTED THIS AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

=R.Reed, P.S E. R. REED , CO. REP.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: BRANCH COUNTY REMONUMENTATION CAP ON STEEL STAKE, OVER STONE & BRICK, IN C-1 MONUMENT BOX:

S 35 W 58.72' - B. POLE.

32.85' FACE OF ROUND CONCRETE FENCE POST.

N 01 W 31.45' FACE OF SQ. CONCRETE FENCE POST.

S 75 E 149.35' TOP OF ROUND CONCRETE FENCE POST, CENTER OF POST.

EDWARD R REED

Surveyor's Michigan License No. \_7437

G. OF WICH EDWARD R.

REED

NO. 7437

OF ESSION A

NOTICE THIS COPY IS FOR BRANCH CONTROPPEDERATMENTAL MAP

PING PURPOSES TREPRODUCTOR FOR THE PROPULT OF LAND SURVEYORS, JAN. 28, 1971
COPY NORM APPROVED BY MICHIGAN STATE BUARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
SEND PUBLIC TO RECOVER REVISED JAN. 1983

DEEDS FOR COMES