SECTION

## BRANCH COUNTY REMONUMENTATION PROGRAM

## LAND CORNER RECORDATION CERTIFICATE STATE OF MICHIGAN Filing Requirement of Act 74, Mich. P.A. 1970 Branch County

For corners in		•	Recorded
BRANCH (County) MATTESON TWP.	Located in:	Corner Code ##	12-30-1999 11:02:57
Public Land Survey	T <u>6 S</u> R <u>8 W</u> T R T R	J-05	Linda Lee Morrison-Mathews REGISTER OF DEEDS
Property Controlling     in Section     Miscellaneous     Property in Sec.	T R S T R S T R S T R S T R R R S T R R R S T R R R S T R R R S T R R R S T R R S T R R R R		Liber 00004 Page 0064 Register of Deeds Stamp & File Number
, raporty in ode.			MATTESON TWP.
	Recorded Plat		A B C D E F G H I J K L M
do hereby certify that under re in lines 1 and 2 above were in current manual of survey instruments of by a decree of above were in conformance with Court of Law; established, expressed below:	S in a field survey on Deci- equirements of P.A. 74, Michigan P.A. in conformance with regulations at ructions of the United States Depart a Court of Law and/or that the comit the rules of the Michigan Board re-established, monumented, recorners, all in the same town and the same t	a. of 1970, the corner points mention of rules therefore as required in rtment of the Interior, Bureau of L er points mentioned in lines 3, 4 a of Land Surveyors or by a Decree monumented, recovered, found	n the Land 7 and 5 8 19 20 21 22 23 24 29 60 fa
A. Description of original	monument and accessories an	nd/or subsequent restoration:	
	ieldnotes of Wm. Brook - 40 10% Set or Sec. (		orrected between Sec's.

- 1969: G. E. Anderson, MSHD: "Re-established on line and midway between N.E. and N.W. corners of Section 14. Set 3/4" pipe in Monument Box. (On a survey by MSHD for Highway M-86).
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: From witnesses of G.E. Anderson, dug and found the pipe in Monument Box, in gravel road.

Set a Branch County Remonumentation Cap on 1/2"X18" rebar rod and cemented same in the 3/4" pipe, in C-I monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Branch County Remonumentation Cap on rebar rod in pipe, in C-I monument box: N 75 E  $\,$  61.71' Tag in 22" Oak

Tag in 22" Oak

Tag in 30" Walnut. 10" twin Ash. 35.5 N 45 W

53.6 S 60 W

Center 12" ASH. 21.1' South



Edward R. Reed

Date December 1, 1999