SURVEY &

MAR 1 3 1998

SECTION

BRANCH COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE OF MICHIGAN

| Filing Requirement of A | let 74, Mich. P.A. 197 | fir anch County Recorded |
|--|-----------------------------|--|
| For corners in | | |
| BRANCH Located In: C | Corner Code# | 10-22-1997 09:53:15 |
| ALGANSEE TWP. | | Linda Lee Morrison-Mathews |
| 1. Public Land Survey T78 R5W G-13 | | REGISTER OF DEEDS |
| T R | | Liber 00003 Page 0136 Register of Deeds Stamp & File Number |
| | | • |
| 4. Lot No, Recorded Plat | | ABCDEFGHIJKL |
| 5. Private Claims | | 2 6 5 - 4 3 2 - 1 |
| | 5 | 3 |
| | | 4 - 7 - 6 - 10 - 11 - 12 |
| I, <u>EDWARD W. REED</u> , in a field survey on <u>JUNE 20</u> | _, 19 <u>97</u> _ do hereby | |
| state that under requirements of P.A. 74, Michigan P.A. of 1970, the corn- lines 1 and 2 above were in conformance with regulations and rules there | or points mentioned in | 7 |
| current manual of survey instructions of the United States Department of Land Management or by a decree of a Court of Law and /or that the corn | | 8 19 20 21 22 23 24 |
| lines 3, 4 and 5 above were in conformance with the rules of the Michigan Bo | ard of Land Surveyors | |
| or by a Decree of a Court of Law; established, re-established, monumented expressed below: | | 0 30 29 29 27 26 25 |
| NOTE: Not more than 2 corners, all in the same town and range, may on this certificate. | be recorded 1 | 2 31 32 33 34 35 36 |
| A. Description of original monument and accessories and/or subsequ CORNER COMMON TO SECTIONS 33 & 34 ALGANSEE—C SECTIONS 3-4 CALIFORNIA | | |
| 1825: JOHN MULLET, DEPT, SURVEYOR- CORNER SET 1877: M. KNOWLES, CO. SURVEYOR-FOUND STONE 1989: E.R.REED, CO SURVEYOR - FOUND 1" SQUARE SH ABOUT 10" DEEP, RECORDED IN LCRC # II-133 | HAPED IRON NEAR C | ENTER OF ROAD INTERSECTION |
| B. Description of corner evidence found and/or method applied in re | storing or reestablishing c | omer: |
| FOUND 1" SQUARE IRON BAR AS RECORDED IN LCRC # II-133 SET ½" X 18" REBAR IRON WITH REMON CAP IN CI-MONUMENT BOX FLUSH WITH ROAD SURFACE | | |
| C. Description of monument for comer and accessories establishe SET ½" X 18" REBAR IRON AND REMON CAP IN CI-MONU | JMENT BOX. ACCER | PTED BY THE BRANCH COUNTY BY PEER GROUP AS THE OFFICIAL BR UNDER MICHIGAN PUBLIC ACT 345 |
| C/L S. END N-S CMP ROAD CULVERT, S32E 36.7' C/L N. END N-S CMP ROAD CULVERT, N35E 37.1' | of <u>1</u> | 1990 AT A MEETING HELD ON |
| C/L W. END E-W CMP ROAD CULVERT, N06W 112.9' | | F.R. REED |
| TEL. PEDESTAL, S37W 58.1' | | Patria |
| AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERP CORNER | ETUATION OF THE P | OSITION OF THE ORIGINAL |
| Signed by Edlin W. Kuy | DF MICH | DateJUNE 20, 1997 |
| EDWARD W. REED | EDWARD | |
| Surveyor's Michigan License No. 33985 | W. REED LAND SURVEYOR | |

MAY 14,1975

JAN. 28, 1971

REVISED JAN, 198 REVISED OCT., 199

OVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS