FEB 0 8 1999

SECTION

Surveyor's Michigan License No.___

33985

BRANCH COUNTY REMONUMATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

i milg requirement of Act 14, mich. F.A. 15.	, 0
BRANCH COUNTY Located In: Corner Code #	STATE OF MICHIGAN Branch County Recorded 11-04-1998 15:48:31 Linda Lee Morrison-Mathews REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J 2 6 5 4 3 2 1 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
B. Description of corner evidence found and/or method applied in restoring or reestablishing FOUND 1" IRON PIPE BELOW ROAD SURFACE SET ½" X 18" REBAR IRON WITH REMON CAP IN CHMONUMENT BOX FLUSH WITH C. Description of monument for corner and accessories established to perpetuate locating ½" IRON WITH REMONUMENTATION CAP IN CAST IRON BOX POWER POLE S 70 E 102.4' TO FACE TEL PED S 40 E 49.1' TO FACE POWER POLE S 23 W 116.4' TO FACE TEL PED S 55 W 43.0' AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER	ROAD SURFACE