- FEB 0 <u>6 1999</u>

SECTION

EDWARD R. REED,
Surveyor's Michigan License No.

## BRANCH COUNTY REMONUMENTATION CORNER

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

|                                |  | Filing Requir  | ement of Act 74, Mich.   | P.A. 1970  |
|--------------------------------|--|--|--|--|
| For                            | BRANCH (County)  | Located In:  | Corner Code ##   | STATE OF MICHIGAN<br>Branch County   |
| 1.                             | GILEAD TWP. Public Land Survey   | T <u>8 S</u> R <u>7 W</u><br>T R   | G - 05   | Recorded<br>11-04-1998 15:49:28  |
|                                | Property Controlling in Section Miscellaneous  | T R<br>T R<br>S T R<br>S T R   |  | Linda Lee Morrison-Mathews<br>REGISTER OF DEEDS<br>Register of Deeds Stamp & File Number   |
|                                | Property in Sec.   | S R  |  | GILEAD TOWNSHIP  |
|                                |  | Recorded Plat  |  | A B C D E F G H I J K L  |
|                                |  |  |  | 3 4 7 8 9 10 11  |
| do lin li<br>cur<br>Mai<br>abo | nereby certify that under re<br>ines 1 and 2 above were<br>rent manual of survey inst<br>nagement or by a decree of<br>ove were in conformance w | S in a field survey on quirements of P.A. 74, Michigan P.A. n conformance with regulations are ructions of the Unifed States Depart a Court of Law and/or that the corneith the rules of the Michigan Board or re-established, monumented, re- | of 1970, the corner points me<br>id rules therefore as required<br>tment of the Interior, Bureau<br>or points mentioned in lines 3,<br>of Land Surveyors or by a Dec | ntioned d in the of Land 7 4 and 5 8 19 20 21 22 23  |
|                                |  | corners, all in the same town a  | nd range, may be recorde   | 11 12 31 32 33 34 35   |
| Α.                             | Description of original CORNER COMMON TO   | monument and accessories and SECTIONS 9, 10, 15 &  | d/or subsequent restoration 16. GILEAD TWP., T   | on:  |
|                                | POST N458<br>1984: L. GERSCHE<br>REPLACED W  | 37.1', STEEL ANCHOR P  | OST N45W 33.0'."<br>0.3" SQ. STONE OF R  | E, ON END, 16" DEEP: STEEL ANCHOR RECORD 16"-18" BELOW ROAD SURFACE.   |
| В.                             | Description of corner  | evidence found and/or method   | applied in restoring or ree  | stablishing corner:  |
| *                              | TOP, IN BLACKTOP I REMOVED THE 5/  | ' PAVEMENT.<br>'8" REBAR AND SET A 1/2   | "X18" REBAR WITHA  | BRANCH COUNTY REMONUMENTATION CAP  |
|                                |  |  |  | ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON SEPT. 9 1998 |
|                                |  |  |  | <i>E.R.REED</i><br>Liber 00003 Page 0239   |
| C.                             | 1/2" REBAR WITH<br>N34E 33.80'<br>S25E 42.0' T<br>S50W 36.50'<br>S33W 34.90'   | REMONUMENTATION CAP, I TO NEAR FACE OF WOOD O TO NE CORNER OF TELEPH TO NE CORNER OF WOOD O TO NEAR FACE OF WOOD O ENTER OF HOLE IN TOP O  | N CONCRETE, IN A CONNER POST  ONE PEDESTAL (SQUARORNER POST (ELECTR  | ARE).  |

ESHOW